DocuSign Envelope ID: B4E997C2-EEDC-445F-9758-5B0F125EE37F

Building No.	Stre	Street			Zip		Date of Inspection		Number o	Number of Pages	
1869	Brook	wood Drive	Vacav	ille	9568	7	August 7	, 2022	3		
Shepp		ermite Se	rvices 7	707-208-2102 or		52-0422		Compa # R92	ny Report 228		
Chara			t	5278 Poplar							
Snepp	ardierm	ite@sbcglobal.	net	Vacaville, CA.	95687						
Ordered By: Windy Rodriguez			Property Owner and/or Party of Interest:			8	Report sent to: Same JocuSigned by: JAC 8/5/2022 1:11 PM PDT REINSPECTION REPORT				
COMPLETE KEP	OKI	X LIMITED RE	FURI	SUFFLEMENTAL	LEFOR		REINSPECTION REPORT				
General Description: Single story home on concrete slab with attached garage. An inspection has been made of the structure(s) shown on the diagram in accordance with the Structural Pest C							Inspection Tag Posted: Garage Other Tags Posted: Control Act. Detached porches, detached steps,				
		tructures not on the di	<u> </u>		rr						
Subterranean Termites Drywood T			ermites	Fungus / Dryrot		Other F	indings	Further	Inspection		
If any of the above	ve boxes are	checked, it indicates t	hat there were	visible problems in acce	ssible are	eas. Read th	e report for de	tails on checke	ed items.		



"			 	
	"			
		"		
 <i>"</i>	,			

NOTE: DIAGRAMS ARE NOT TO SCALE

Rosh

Inspected by: <u>Richard Sheppard</u> State License No. <u>OPR10979</u> Signature

You are entitled to obtain copies of all reports and completion notices on this property reported to the Structural Pest Control Board during the preceding two years. To obtain copies contact: Structural Pest Control Board, 2005 Evergreen Street, Suite 1500, Sacramento, CA. 95815-3831.

NOTE: Questions or problems concerning the above report should be directed to the manager of the company. Unresolved questions or problems with services performed may be directed to the Structural Pest Control Board at (916) 561-8708, (800) 737-8188 or www.pestboard.ca.gov. 43M-41 (REV. 10/01)

Company Report # R9228

NOTICE: Reports on this structure prepared by various registered companies should list the same findings (i.e. termite infestations, termite damage, fungus damage, etc.) However, recommendations to correct these findings may vary from company to company. You have a right to seek a second opinion from another company.

This company will reinspect repairs done by others within four months of the original inspection. A charge, if any, can be no greater than the original inspection fee for each reinspection. The reinspection must be done within (10) working days of request. The reinspection is a visual inspection and if inspection of concealed areas is desired, inspection of work in progress will be necessary. Any guarantees must be received from parties performing repairs.

Note: The inspection was made of the structure as described, and indicated by diagram on page 1 of this report. Photo on front page is not a diagram. Inspections of fences, and/or detached structures that may exist on the property were not made unless otherwise stated in this report.

Note: This property was not inspected for the presence or absence of health related molds or fungi. By California law we are neither qualified, authorized nor licensed to inspect for health related molds or fungi.

Note: The inspection was made of accessible and visible areas only, and is limited to visible evidence only.

No opinion is made or implied of inaccessible areas, and no guarantee is made that infestations/infections, which are not visibly evident, do not exist.

Some commonly inaccessible areas include, but are not limited to, interiors of hollow walls, areas concealed by floor covering, wall covering, cabinetry, masonry, vegetation, insulation, appliances, furnishings, storage, areas of low construction, areas of space limitations, and any other area that inspection access is obstructed, either wholly or partially.

Areas that access can only be made from the rooftop, or any other area that in order to gain access, would cause damage to, or where the threat of damage to property exists, are also considered inaccessible areas.

Note: All areas of plumbing are not tested. Some plumbing areas are tested briefly. Plumbing leaks may develop at any time for numerous reasons. Items, such as leaking valves, toilets that continually run, or other areas where moisture does not make contact with, or threaten wood members, may not be noted in this report. Sheppard Termite Services offers no warranty or guarantee regarding plumbing. Stall showers over finished ceilings and concrete slabs are not tested. If an in depth inspection/test of plumbing is desired, a licensed plumbing contractor should be consulted.

The exterior surface of the roof was not inspected. If you want the water tightness of the roof determined, you should contact a roofing contractor who is licensed by the Contractor's State License Board.

This is a separated report which is defined as Section I/Section II conditions evident on the date of inspection. Section I contains items where there is visible evidence of active infestation, infection or conditions that have resulted in or from infestation or infection. Section II items are conditions deemed likely to lead to infestation or infection but where no visible evidence of such was found. Further inspection items are defined as recommendations to inspect area(s) which during the original inspection did not allow the inspector access to complete the inspection and cannot be defined as Section I or Section II.

Section III includes items that cannot be defined as Section I or Section II.

R9228



SECTION 1 - Visible evidence of infestation/infection or conditions resulting from infestation/infection.

None

SECTION 2 - Conditions that are conductive to infestation/infection.

None visible

SECTION 3 - Items and notations that are not defined in either of the above sections.

Note: The substructure of the deck was inaccessible for inspection. If inspection of these areas is desired, removal of deck boards by others would be necessary.

Note: Patio cover conceals some exterior areas of the home.

Note: Stall shower does not have typical enclosure door. Special care should be taken during shower use to prevent moisture from exiting shower areas. A periodic inspection is advised.

Note: The attic was inaccessible for complete and thorough inspection due to space limitations, and areas concealed by insulation and/or ductwork.

Note: The structure contained furnishings and/or storage at the time of inspection. Sheppard Termite Services does not move furnishings, storage or any objects that obstruct access for inspection, and will not be responsible for conditions that may be concealed by furnishings, storage or any other objects.

This is to certify that the above property was inspected on August 1, 2022 in accordance with the Structural Pest Control Act and rules and regulations adopted pursuant thereto, and that no evidence of active infestation or infection was found in the visible and accessible areas.