

PAUL E. JONES NAPI CERT. # 30667

P.O. BOX 981071 W. SACRAMENTO, CA 95798 (916) 752-0275 e-mail: pjones21@comcast.net

INSPECTION DATE: October 12, 2021 REPORT NUMBER: A71421

CLIENT: Diane & Gregory lannone

PROPERTY INSPECTED: 865 Studding Sail St

Vacaville, CA 95687

The property inspected is a 4 bedroom, 2 bath single family home. The weather at the commencement of the inspection was clear with a temperature reading of approximately 68 degrees Fahrenheit.

COMMENTS

The home is nicely designed, well constructed and structurally sound. Many of the suggested repairs are the result of normal wear.

Our evaluation is visual in nature of readily accessible areas. Excavation, lifting of floor coverings, opening walls or ceilings, moving furniture, personal or stored items, disassembly of equipment, or other potentially damaging or dangerous procedures were not performed. We do not specifically inspect for compliance with any building codes or regulations of any governmental or non-governmental body or entity. Our review does not take into consideration the normal wear associated with virtually all properties.

INSPECTION SUMMARY

FOUNDATION SYSTEM

The foundation is an above grade foundation (pier & beam). The foundation walls are constructed of poured concrete. No evidence of excessive stress or settling to the foundation system was detected.

The foundation system is in an acceptable condition. No needed repairs to the foundation system were detected at the time of the inspection.

FRAMING STRUCTURE

The framing structure appears firm and intact within all accessible areas. The interior/exterior walls are plumb and square within acceptable ranges.

The framing structure is in an acceptable condition. No needed repairs to the framing structure were detected at the time of the inspection.

ROOF SYSTEM

Our evaluation of the roof is to determine if portions are missing and/or deteriorating and, therefore, subject to possible leaking. Portions of underlayment and decking are hidden from view and cannot be evaluated by our visual inspection; therefore, our review is not a guarantee against roof leaks nor a certification.

The roof surface is constructed of composition shingles. The estimated age of the roofing material is 10 years.

Maintenance issues:

 The seams at the chimney flashing appear poorly sealed (as viewed from the roof eaves). Suggest the roof be further inspected by a licensed roofing contractor and be repaired as found needed. (See Photo #1)

ATTIC LEVEL

The attic framing structure is firm and intact. The attic area is adequately ventilated and well insulated with a cellulose loose fill insulating material.

The attic level is in an acceptable condition. No needed repairs to the attic level were detected at the time of the inspection.

ELECTRICAL SYSTEM

The electrical system is a 100 AMP service with solar panels. The service entrance panel is located at the East exterior and the sub panel is located at the garage interior. Overload protection is provided by circuit breakers.

No evidence of overheating or corrosion to the electrical system was detected. The size of the electrical system appears adequate.

The electrical system is in an acceptable condition. No needed repairs to the electrical system were detected at the time of the inspection.

PLUMBING SYSTEM

The water supply and sewage system are public. The water supply lines are copper and the drain, waste and vent pipes are ABS. The water pressure appeared adequate at the time of the inspection.

Maintenance issues:

Water Heater

- 1. The discharge pipe to the water heater temperature/pressure relief valve is missing. Suggest a code compliant discharge pipe be installed by a qualified licensed contractor. (Safety Concern, See Photo #2)
- 2. The water heater is improperly braced for earthquake safety. Suggest the water heater be braced with code compliant seismic straps by a qualified licensed contractor. (Safety Concern,, See Photo #3)

Hall Bathroom

- 1. The toilet is loosely secured to the floor. Suggest the anchoring bolt nuts be tightened by a qualified licensed contractor. (See Photo #4)
- 2. The bathtub drain leaks in the sub area. Suggest the drain line be repaired by a qualified licensed contractor. (See Photo #5)

Master Bathroom

- 1. The sink drain leaks in the sub area. Suggest the drain line be repaired by a qualified licensed contractor. (See Photo #6)
- 2. The floor underlayment appears moisture damaged near the shower from apparent leakage at the shower enclosure. Please refer to the structural pest report for additional comments and recommendations, if any. (See Photo #7 and Photo #8).

FIREPLACE

Maintenance issues:

1. The inspection of the fireplace was limited due to the placement of the insert. Suggest the fireplace be further inspected by a licensed chimney sweep. (See Photo #9)

EXTERIOR SURFACES

Maintenance issues:

1. The roof eaves appear moisture damaged at various locations. Please refer to the structural pest report for additional comments and recommendations, if any. (See Photo #10 and Photo #11)

NOTE

We wish to remind you that every house requires a certain amount of ongoing maintenance and this house is no exception. Drains sometimes clog, furnaces, air conditioners, water heaters all need periodic servicing and at some point in time may need to be replaced. These are but a few examples of things you can expect as a homeowner. It is suggested that you expect and budget for ongoing maintenance and repairs.

Please read the inspection worksheet for additional findings and recommendations.

Paul E. Jones



PHOTO #1



PHOTO #2



PHOTO #3



PHOTO #4



PHOTO #5



РНОТО #6



РНОТО #7



PHOTO #8



РНОТО #9



PHOTO #10



PHOTO #11

LOTS & GROUNDS		A	N	N	M
COMMENTS		C	ρ	1	A
UUMMEIT 13		C	Я	N	13
	Walks				
	Steps	_	X		
	Driveways	_ 💢		_	
	Fences			_	
	Retaining walls		X	_	
	Grading		_		·
	Swales	_	X	_	
	Stairwell drain		X	_	
	Window wells	_	X		
	Surface drain				
NIM	loose/missing handrals		Der Mangel		
Earth to wood contact noted Apparent moisture damage Damaged	koose/missing handrals				
Earth to viood contact notedApparent moisture damageDamaged/	ards nend sealarr Other				
Earth to visced contact noted	Octor Other On rusted/corroded noisture/insect damage	Not plumb			

ROOF					- 1	A N C P	N	M A R	0 E F
001415150	•			D - # - # 1		CR	-N	-	
COMMENTS		4 /	<u></u>	Roofing # 1	}	X			1-1
- THE	SEAMS AT	THE	CHIMARY	Roofing # 2	 				i
FLASI	11NG APPE	7R1	060/267	Roofing # 3 Roofing # 4		一ス	5		
5/	EALES	·			 - -	7	4		V
				Flashing Skylights		$\frac{1}{2}$			75
				Chimneys					X
1				Gutters		Δ.	1		
				Downspouts	— :	Θ	1		
EVIDENCE OF LEAKS	CONCLUSIVELY DETERMINE IF A BLE- IS BASED ON THE AGE AND OR MAY SOON DEVELOP LEAKS. E WITHIN THE LIMITS OF I'S AGE	JONEHAL	KS UNLESS IT IS RAINING AT USEFULNESS OF A ROOF. A I, SUCH A ROOF CAN BE REF	THE TIME OF IN: AN FACCEPTABLE PAIRED AND GIVE	SPECTIO E-HOOF E-GENER	IN. A MAY S JALLY	HOW		
	MATERIAL/LOCATION	LAYERS	INSPECTION ME	ТНОР	APPR			SIGI	N
ROOFING # 1	CUMPOSITION	12	walked on Xladder at e		AGE 10	125	<u> </u>	FE ()	
ROOFING # 2			. walked onladder at e	avosground					7
ROOFING # 3			walked onladder at e	avesground	 .		_ 		
ROOFING # 4		-	walked onladder at e	avesground					
Missing shakes/shir Doteriorated granul Bare spots Spongy in areas	us Many t Pitch/s Eviden	Cracked tiles blisters slope substan ice of leaks ent improper	Crac Crac Recc Roof	ping/curling king/alligatoring ommend trimming t partially obscured ris/snow/vegetatio	by solar		/		
FLASHINGS/VALLEYS No visible flashing	Composition Met Recaulking/mastic needed			oper installation	— Exp	nsed na	ads in	flash	ning
SKYLIGHTS Apparent impreper	NIA installation Crack	:ed/dan1aged	glass Evide	ance of leaks	-,				· ,
CHIMNEYS Bridge Becommend recault Becommend capts: Missing/datarierated	park arroster Appai	Other_ bricks ront substance rant out of plu	Sepa	iration from structu appoars unlined	to				
GUTTERS, DOWNSPOI Loose gutters/down Damaged gutters/de Evidence of teaks	nspouls Gutter ownspouls Gutter	rs/downspoul rs sagging ent improper	Guite	Brate/oxcussive co or/downspout missi klensions/splash b	ing				

EXTERIOR SURFACE		IA IN IN IM ID I
COMMENTS		CPIAE
	Siding # 1	
THE ROUF FAVES APPEAR	Siding # 2	
MUISTURE DAMAGED AT	Windows	
VARIOUS COCATIONS	Soffits/Fascia	
	Exterior Doors	
	Shutters/Awnings	
SIDING		• •
MATERIAL: Siding #1 5TUCCO Siding #2 BRICK Si LOCATION:	ding # 3	
Common Cracks Apparent moisture damage Touch u Large/unusual cracks Damaged/loose siding Patching	o/overall painting recomme holes/cracks/gaps recomme ection obscured by vegetat	nended
SOFFITS, FASCIAS, TRIM X Wood Viny! Metal: Other:		
Damaged/loose/missing X Apparent moisture damage Poor ear	th-to-wood clearance	
PORCHES, DECKS, PATIOS		
. 55.125, 52510, 1711100		IA IN IN IN ID
COMMENTS		CPIAE
O Training 15	1	CRNRF
	Porches	
	Decks	
	Patios	X
	Balconies	
PORCHES		
Apparent settling Loose support posts/pillars/railings Appare Apparent roof leaks Poor earth-to-wood-clearance Appare	nt damaged flooring nt damage	
DECKS ALL A		
No tootings evident Apparent damage Popped nails/loose boards	Not belied to be	4
Loose/missing handrails Poor earth-to-wood clearance Apparent cracked/broken/sagg	ing structural members	indigions mangers
PATIOS ConcreteBrickFlagstoneTile Other		
Common/large cracks Lifting/settling Tripping hazard	Sloped toward hou	Covered/could not inspect
BALCONIES NIA		
Language training and the second seco	antly not boited to house	No joist hangers

. -

TITCHEN			[A N N N M]
DMMENTS			C P I A
		Ceiling/walls	
		Floor	
		Doors/windows	1.8
		Sink/cabinets	
	<u></u>	Appliances	
		Disposal	
		Dishwasher	
		Ventilator	
		Built-ins	
Common cracks Ap	maged/loose baseboard/paneling	Apparent damage Ou Pul	atlet/switch appears defeated inspection obstructed
Uneven/sloped Fe Cracked/broken tiles Ma DORS/ WINDOWS Windows:	w/many vinyl tears/gouges ajor/minor carpet damage Double hung Casement X Slidi	Cupping/bucking wood Ful _ Loose/uplifted tiles Spo	ll inspection obstructed ongy/bouncy
Uneven/sloped Fe Cracked/broken tiles Ma DORS/ WINDOWS Windows: Dual pane appears fogged Do Cracked/broken glass Do	w/many vinyl tears/gouges ajor/minor carpet damage Double hung Casement Slidi eor/window inoperative eor damaged/delaminated	Cupping/bucking wood Ful Loose/uplifted tiles Spo	il inspection obstructed ongy/bouncy
Cracked/broken tiles Ma DORS/ WINDOWS Windows: Dual pane appears fogged Do Cracked/broken glass Do NK/ CABINETS/ COUNTERS Restricted view below sink	w/many vinyl tears/gouges ajor/minor carpet damage Double hung Casement Slidi eor/window inoperative eor damaged/delaminated	Cupping/bucking wood Ful Loose/uplifted tiles Spo	il inspection obstructed ongy/bouncy
Uneven/sloped Fe Cracked/broken tiles Ma DORS/ WINDOWS Windows: Dual pane appears fogged Do Cracked/broken glass Do NK/ CABINETS/ COUNTERS Restricted view below sink Sink loose from wall/cabinet Sink cracked/chipped/damaged	w/many vinyl tears/gouges ajor/minor carpet damage Double hung Casement Slidi or/window inoperative or damaged/delaminated Sink hot and cold reversed Sink hot and cold reversed Faucet fixtures corroded Sink drain appears to leak	Cupping/bucking wood Ful Loose/uplifted tiles Spo	Il inspection obstructed ongy/bouncy
Uneven/sloped Fe Cracked/broken tiles Ma DORS/ WINDOWS Windows: Dual pane appears fogged Do Cracked/broken glass Do NK/ CABINETS/ COUNTERS Restricted view below sink Sink loose from wall/cabinet	w/many vinyl tears/gouges ajor/minor carpet damage Double hung Casement Slidi por/window inoperative por damaged/delaminated Sink hot and cold reversed Sink drain appears to leak Sink drain stopper inoperative Sink/drain improperly installed	Cupping/bucking wood Ful Loose/uplifted tiles Spo	Il inspection obstructed ongy/bouncy inets cabinets cinets
Uneven/sloped Fe Cracked/broken tiles Ma DORS/ WINDOWS Windows: Dual pane appears fogged Do Cracked/broken glass Do NK/ CABINETS/ COUNTERS Restricted view below sink Sink loose from wall/cabinet Sink cracked/chipped/damaged Corrosion on/under sink/drain	w/many vinyl tears/gouges ajor/minor carpet damage Double hung Casement Slidi or/window inoperative or damaged/delaminated Sink hot and cold reversed Faucet fixtures corroded Sink drain appears to leak Sink drain stopper inoperative Sink/drain improperly installed	Cupping/bucking wood Ful Loose/uplifted tiles Spo	Il inspection obstructed ongy/bouncy inets cabinets prints
Uneven/sloped Fe Cracked/broken tiles Ma DORS/ WINDOWS Windows: Dual pane appears togged Do Cracked/broken glass Do NK/ CABINETS/ COUNTERS Restricted view below sink Sink loose from wall/cabinot Sink cracked/chipped/damaged Corrosion on/under sink/drain Sink stained/discolored Sink drains slowly	w/many vinyl tears/gouges ajor/minor carpet damage Double hung Casement Slidi por/window inoperative por damaged/delaminated Sink hot and cold reversed Faucet fixtures corroded Sink drain appears to leak Sink drain stopper inoperative Sink/drain improperly installed Faucet leaks	Cupping/bucking wood Ful Loose/uplifted tiles Spo	Il inspection obstructed ongy/bouncy inets cabinets oinets
Uneven/sloped Fe Cracked/broken tiles Ma DORS/ WINDOWS Windows: Dual pane appears fogged Do Cracked/broken glass Do NK/ CABINETS/ COUNTERS Restricted view below sink Sink loose from wall/cabinot Sink cracked/chipped/damaged Corrosion on/under sink/drain Sink stained/discolored Sink drains slowly PPLIANCES/ BUILT-INS RANGE/COOKTOP None	w/many vinyl tears/gouges ajor/minor carpet damage Double hung Casement Slidi por/window inoperative por damaged/delaminated Sink hot and cold reversed Faucet fixtures corroded Sink drain appears to leak Sink drain stopper inoperative Sink/drain improperly installed Faucet leaks Faucet has constant drip Not tested Operational	Cupping/bucking wood Ful Loose/uplifted tiles Spo	Il inspection obstructed ongy/bouncy inets cabinets oinets
Uneven/sloped Fe Cracked/broken tiles Ma DORS/ WINDOWS Windows: Dual pane appears fogged Doc Cracked/broken glass Doc NK/ CABINETS/ COUNTERS Restricted view below sink Sink loose from wall/cabinot Sink cracked/chipped/damaged Corrosion on/under sink/drain Sink stained/discolored Sink drains slowly	w/many vinyl tears/gouges ajor/minor carpet damage Double hung Casement Slidi por/window inoperative por damaged/delaminated Sink hot and cold reversed Faucet fixtures corroded Sink drain appears to leak Sink drain stopper inoperative Sink/drain improperly installed Faucet leaks Faucet has constant drip	Cupping/bucking wood Full Loose/uplifted tiles Sport S	il inspection obstructed ongy/bouncy inets cabinets binets catinets
Uneven/sloped Fe Cracked/broken tiles Ma CORS/ WINDOWS Windows: Dual pane appears fogged Do Cracked/broken glass Do NK/ CABINETS/ COUNTERS Restricted view below sink Sink loose from wall/cabinot Sink cracked/chipped/damaged Corrosion on/under sink/drain Sink stained/discolored Sink drains slowly PPLIANCES/ BUILT-INS RANGE/COOKTOP None OVEN None DISHWASHER None GARBAGE DISPOSAL	w/many vinyl tears/gouges ajor/minor carpet damage Double hung Casement Slidi por/window inoperative por damaged/delaminated Sink hot and cold reversed Faucet fixtures corroded Sink drain appears to leak Sink drain stopper inoperative Sink/drain improperly installed Faucet leaks Faucet has constant drip Not tested Operational Operational	Cupping/bucking wood Full Loose/uplifted tiles Spanning Fixed Other Missing/damaged hardware Evidence of leakage Minor wear/damage to counters/cabi Moderate wear/damage to counters/cabi Heavy wear/damage to counters/cabi Cabinet handles/latches missing Latches/guides need adjustment/rep Grout/caulking needed around counters/cabi	il inspection obstructed ongy/bouncy
Uneven/sloped Fe Cracked/broken tiles Ma DORS/ WINDOWS Windows: Dual pane appears fogged Do Cracked/broken glass Do NK/ CABINETS/ COUNTERS Restricted view below sink Sink loose from wall/cabinot Sink cracked/chipped/damaged Corrosion on/under sink/drain Sink stained/discolored Sink drains slowly PPLIANCES/ BUILT-INS RANGE/COOKTOP None OVEN None DISHWASHER None	w/many vinyl tears/gouges ajor/minor carpet damage Double hung Casement Slidi por/window inoperative por damaged/delaminated Sink hot and cold reversed Faucet fixtures corroded Sink drain appears to leak Sink drain stopper inoperative Sink/drain improperly installed Faucet leaks Faucet has constant drip Not tested Operational Not tested Operational Operational Operational Operational Operational Operational	Cupping/bucking wood Ful Loose/uplifted tiles Spa ng Fixed Other Missing/damaged hardware Evidence of leakage Minor wear/damage to counters/cabi Moderate wear/damage to counters/cabi Heavy wear/damage to counters/cabi Cabinet handles/latches missing Latches/guides need adjustment/rep Grout/caulking needed around count	il inspection obstructed ongy/bouncy
Uneven/sloped Fe Cracked/broken tiles Ma DORS/ WINDOWS Windows: Dual pane appears fogged Do Cracked/broken glass Do NK/ CABINETS/ COUNTERS Restricted view below sink Sink loose from wall/cabinot Sink cracked/chipped/damaged Corrosion on/under sink/drain Sink stained/discolored Sink drains slowly PPLIANCES/ BUILT-INS RANGE/COOKTOP None OVEN None DISHWASHER None MICROWAVE None	w/many vinyl tears/gouges ajor/minor carpet damage Double hung Casement Slidi or/window inoperative or damaged/delaminated Sink hot and cold reversed Faucet fixtures corroded Sink drain appears to leak Sink drain improperly installed Sink/drain improperly installed Faucet leaks Faucet has constant drip Not tested Operational Not tested Operational Not tested Operational Not tested Operational	Cupping/bucking wood Full Loose/uplifted tiles Spanning Fixed Other Missing/damaged hardware Evidence of leakage Minor wear/damage to counters/cabi Moderate wear/damage to counters/cabi Heavy wear/damage to counters/cabi Cabinet handles/latches missing Latches/guides need adjustment/rep Grout/caulking needed around counters/cabi	il inspection obstructed ongy/bouncy

ROOM FAMILY ROUM	A N N N D C P I A E
COMMENTS	particular to the second of th
The life of all of	Ceiling Walls
THE TOTAL WAS	Doors/Windows
116	Floor
LIMITED DUE TO THE	
PLACEMENT OF THE	Fireplace/etc.
INSERT	Outlets/switches
Common cracks Apparent moisture stains Apparent dar Large/unusual cracks Darnaged/10056 baseboard/paneling Apparent par	Page Oldielswith 2002 to to to to to
FLOOR Carper Vinyl Lila Sheet vinyl X Wood Ceramic tile	Other
	XIN) WOOD ANNUA MALLON DOOW (XIX)
DOORS/ WINDOWS Windows: Double hung CasementXStiding Fixed	(115,11
	other SLIDING aged hardware GUSS 7 UUA sakage
	(SECONOMICS)
ROOM LIVING ROOM (Location)	A W N M D
A STATE OF THE PARTY OF THE PAR	C P I A E C R N R
(Location)	Ceiling C P I A E C R N R
(Location)	Ceiling Walls
(Location)	Ceiling Walls Doors
(Location) COMMENTS	Ceiling Walls
(Location) COMMENTS	Ceiling Walls Doors
(Location) COMMENTS	Ceiling Walls Doors Floor
COMMENTS COMMENTS Common cracks (Location) Common cracks (Location) Plaster Acoustic spray Other Walls - Plaster Wellpaper Panating Other	Ceiling Walls Doors Floor Windows Outlets/switches
COMMENTS COMMENTS CEILING/ WALLS Ceiling Drywall Plaster Acoustic spray Other Walls Drywall Plaster Wallpaper Paneting Oth Common cracks Apparent moisture stains Large/unusual cracks Osmaged/loose baseboard/paneting Apparent pail	Ceiling Walls Doors Floor Windows Outlets/switches Outlets/switches
COMMENTS COMMENTS CEILING/ WALLS Ceiling Drywall Plaster Acoustic spray Other Walls Drywall Plaster Wallpaper Paneting Oth Common cracks Apparent moisture stains Large/unusual cracks Osmaged/loose baseboard/paneting Apparent pail	Ceiling Walls Doors Floor Windows Outlets/switches Mage Culleuswitch appears defective Full inspection obstructed by furnishings
COMMENTS COMMENTS Common cracks — Apparent moisture stains — Apparent date — Large/unusural cracks — Darnaged/loogs baseboard/paneling — Apparent pate — FLOOR — Caross — Moultile — Common cracks — Darnaged/loogs baseboard/paneling — Apparent pate — Large/unusural cracks — Darnaged/loogs baseboard/paneling — Apparent pate — Apparent pate — Apparent pate — Common cracks — Darnaged/loogs baseboard/paneling — Apparent pate — App	Ceiling Walls Doors Floor Windows Outlets/switches Pull inspection obsurcted by furnishings her ckling wood Apparent moisture damage
COMMENTS COMMENTS CEILING/ WALLS Ceiling . Y Drywall Plaster Acoustic spray Other Walls . Y Drywall Plaster Acoustic spray Other Walls . Y Drywall Plaster Wallpaper Paneling Other Large/unusural cracks Apparent moisture stains Apparent date	Ceiling Walls Doors Floor Windows Outlets/switches Pull inspection obsurcted by furnishings her ckling wood Apparent moisture damage
COMMENTS CEILING/ WALLS Ceiling · Crywall Plaster Acoustic spray Other Walls · Crywall Plaster Wallpaper Paneling Other Large/unusused cracks Large/unusused cracks Cambon Cracks Apparent moisture stains Apparent date of carpain Cambon Cracks Cambon Cracks Carpain Vinyl tile Sheet vinyl Ywood Ceremic tile Other Cracked/broken tiles Major/minor carpain damage Cossenior Loose/upinte Cracked/broken tiles DOORS/ WINDOWS Windows: Double hung Cassmark Xsliding Fixed	Ceiting Walls Doors Floor Windows Outlets/switches Ther Ching Apparent moisture damage wind wood Apparent moisture damage Cher

ROOM MASTER BEDROOM		A N N M D G P I A E
		CBNBF
COMMENTS	Ceiling	
	Walls	X
	Doors/Windows	
	Floor	
	Fireplace/etc.	
	Outlets/switches	A commenced
CEILING/.WALLS Ceiling: Drywall Plaster Acoustic spray Other Walls: Drywall Plaster Wallpaper Panaling Other Common cracius Apparent moisture stains Apparent dar Large/unusual cracks Damaged/loose baseboard/paneling Apparent pat FLOOR Carper Vinyl Lile Sheet vinyl X wood Ceremic tile	nage Outlevs ching Full inst by furr	switch appears defective pection obstructed nishings
One of Section 19	Other	
	king wood Appared	egamab etulisiom m
DOORS/ WINDOWS WINDOWS: DOUBLE him	**************************************	
Siding Fixed	Other	TANTO (MATERIAL MATERIAL MATER
	saksda God usaksag	Law 1035 de la constant de la consta
37.00		
		ESTATION TO PETER SOURCE STATE OF THE SOURCE S
ROOM NW BEDROOM (Location)		ANNMO
1721001	Coiling	
(Location)	Ceiling	CPIAE
(Location)	Ceiling Walls	CPIAE
(Location)		CPIAE
(Location)	Walls Doors	CPIAE
(Location)	Walls Doors Floor	CPIAE
(Location)	Walls Doors Floor Windows	CPIAE
(Location) COMMENTS	Walls Doors Floor	CPIAE
CEILING/WALLS Cailing - X Drywall Plaster Acquetic Form	Walls Doors Floor Windows Outlets/switches	CPIAE
CEILING/WALLS Cailing - X Drywall Plaster Acquetic Form	Walls Doors Floor Windows Outlets/switches	CPIAE
COMMENTS Common cracks Cailing - Drywall Plaster Acoustic spray Other Walls - Drywall Plaster Wellpaper Paneting Other Common cracks Apparent moisture stains Apparent day Large/unusual cracks Darnaged/loose baseboard/paneting Apparent paneting Darnaged/loose baseboard/paneting Apparent paneting Apparent paneting Darnaged/loose baseboard/paneting Apparent paneting Darnaged/loose baseboard/paneting Apparent paneting Darnaged/loose baseboard/paneting Apparent paneting Darnaged/loose baseboard/paneting Darnaged/loose baseboard/paneting Darnaged/loose baseboard/paneting Darnaged/loose baseboard/loose baseboard/loos	Walls Doors Floor Windows Outlets/switches AreOutlets Ching Full inst	CPIAE
COMMENTS Common cracks Cailing - Drywall Plaster Acoustic spray Other Walls - Drywall Plaster Wellpaper Paneting Other Common cracks Apparent moisture stains Apparent day Large/unusual cracks Darnaged/loose baseboard/paneting Apparent paneting Darnaged/loose baseboard/paneting Apparent paneting Apparent paneting Darnaged/loose baseboard/paneting Apparent paneting Darnaged/loose baseboard/paneting Apparent paneting Darnaged/loose baseboard/paneting Apparent paneting Darnaged/loose baseboard/paneting Darnaged/loose baseboard/paneting Darnaged/loose baseboard/paneting Darnaged/loose baseboard/loose baseboard/loos	Walls Doors Floor Windows Outlets/switches wer mageOutleus chingFull instDy hur	Switch appears defective operation obstructed
CEILING/ WALLS Ceiling - Drywall Plaster Acoustic spray Other Walks - Drywall Plaster Wellpaper Paneting Ott Common cracks Apparent moisture stains Apparent day Large/unusual cracks Damaged/2004% baseboard/paneting Apparent par FLOOR Carped Vinyatiles Should Should be sh	Walls Doors Floor Windows Outlets/switches May mage Outlevs ching Full insign by hure ckling wood Appara	Switch appears defective operation obstructed
COMMENTS COMMENTS CEILING/ WALLS Cailing - Drywall Plaster Acoustic spray Other Walls - Drywall Plaster Wallpaper Paneting Other Large/unusural cracks Large/unusural cracks Damaged/loose baseboard/paneting Apparent part FLOOR Carper Vinyl tile Sheet vinyl Y wood Ceremic use Other Cracked/broken tiles Few/many vinyl tears/gouges Cupping/buc	Walls Doors Floor Windows Outlets/switches May mage Outlevs ching Full insign by hure ckling wood Appara	switch appears defective operation obstructed mathings
COMMENTS CEILING/ WALLS Cailing - X Drywali Plaster Acoustic spray Other Walks - Drywali Plaster Malipaper Paneting Other Common cracks Apparent moisture stains Apparent date Largevunus usel cracks Damaged/loose baseboard/paneting Apparent paid Largevunus usel cracks Damaged/loose baseboard/paneting Apparent paid Unaver/sloped Few/many vinyl tears/gouges Cupping/but Cracked/broken tiles Major/minor carpet damage Looses/upirits DOORS/ WINDOWS Windows: Double hung Cassmant X Stiding Fixed	Walls Doors Floor Windows Outlets/switches May mage Outlevs ching Full insign by hure ckling wood Appara	switch appears detective appetion obstructed nustrings
COMMENTS CEILING/ WALLS Cailing - Drywall Plaster Acoustic spray Other Walks - Drywall Plaster Wellpaper Paneting Ott Common cracks Apparent moisture stains Apparent dat Large/unusual cracks Damaged/loose baseboard/paneting Apparent pat FLOOR Carpet Vinyl tile Sheet vinyl Wood Ceremic tile Ott Unaver/sloped Few/many vinyl tears/gouges Cupping/but Cracked/broken tiles Masjor/minor carpet damage Looses/upirite	Walls Doors Floor Windows Outlets/switches mage Outlovs ching Full insign on the Control of the Control o	switch appears defective perchanges

.

ROOM SW BEDRUM (Location)	A N N M G P I A C R N B	D E
COMMENTS	Ceiling	<u></u>
	Walls	
	Doors/Windows	
	Floor	
	74	
	Fireplace/etc.	
	Outlets/switches	
CEILING/.WALLS Cotting:	Dutlevswitch appears defections Ching Full inspection obstructed by furnishings Other Appears mostly a tempora	-
DOORS/ WINDOWS Windows: Double hung Casement Stiding Fixed Dual pane appears topged Door/window inoperative Missing/dama Cracked/broken glass Door damaged/detaminated Evidence of kills.	Other	
		UNICOMONO NO SE
ROOM SE BEDROUM (LOCALION)	ANNM	D
The state of the s	CPIA	E
(Location)	CPIA	
(Location)	Ceiling C P I A C R N R	E
(Location)	Ceiling Walls	E
(Location)	Ceiling Walls Doors	E
(Location)	Ceiling Walls Doors Floor	E
(Location)	Ceiling Walls Doors Floor Windows	E
(Location) COMMENTS	Ceiling Walls Doors Floor	E
CEILING/WALLS Ceiling V Drawal Places According to the Control of	Ceiling Walls Doors Floor Windows Outlets/switches	E
CEILING/ WALLS Ceiling Drywall Plaster Acoustic spray Other Walks Drywall Plaster Wellpaper Paneting Other	Ceiling Walls Doors Floor Windows	E
COMMENTS COMMENTS Commenciates Ceiling Drywall Plaster Acoustic spray Other Walls Drywall Plaster Wallpaper Paneting Oth Common cracks Apparent moisture stains Large/unusual cracks Damaged/loose baseboard/paneting Apparent pail	Ceiling Walls Doors Floor Windows Outlets/switches Outlets/switch speeds defect	E C
COMMENTS COMMENTS Commenciates Ceiling Drywall Plaster Acoustic spray Other Walls Drywall Plaster Wallpaper Paneting Oth Common cracks Apparent moisture stains Large/unusual cracks Damaged/loose baseboard/paneting Apparent pail	Ceiling Walls Doors Floor Windows Outlets/switches Anage Ching C R N R C R N	E C
COMMENTS COMMENTS Comment cracks Large/unusual cracks Daywall Plaster Acoustic spray Other Walls - Drywall Plaster Wallpaper Paneting Oth Common cracks Apparent moisture stains Apparent day Apparent pail FLOOR Carpet Vinvallies	Ceiling Walls Doors Floor Windows Outlets/switches Apparent mosture damage ching Apparent mosture damage	ELI C.
CEILING/ WALLS Ceiling Drywall Plaster Acoustic spray Other Walks Drywall Plaster Acoustic spray Other Common cracks Plaster Wallpaper Paneling Other Large/unusual cracks Damaged/costs baseboard/paneling Apparent dar Apparent moisture stains Apparent dar Apparent moisture stains Apparent dar Apparent par Damaged/costs baseboard/paneling Apparent par FLOOR Carpes Vinyl tike Sheet vinyl Xwood Certamic title Other Unovervisioped Few/many vinyl tears/gouges Cupping/buc Cracked/broken titles Major/minor carpet damage Looss/upidie	Ceiling Walls Doors Floor Windows Outlets/switches Apparent mosture damage ching Apparent mosture damage	2>0
COMMENTS CEILING/ WALLS Cailing · Drywall Plaster Acoustic spray Other Walks · Drywall Plaster Wallpaper Paneting Other Large/unusused cracks Large/unusused cracks Darnaged/coase baseboard/paneting Apparent date Darnaged/coase baseboard/paneting Apparent pau App	Ceiting Walls Doors Floor Windows Outlets/switches Apparent moisture damage Itiling wood Apparent moisture damage Itiling wood Cither College Co	ELI C.

BATHROOM H	子レレ (Location)		A N N M
COMMENTS			CRNR
THE 70	100 / 100 /	Ceiling Walls	13-1-
SEWARD	70 THIS 1-100		12
ME BANK	11.0 50 01.1	Doors	
1 ENKS (A)	TUB DRAIN	Floor	$-\left \frac{1}{2} \right $
	342347	Windows	
		Tollet/sinks	-
		Tub/shower	
SUPPLY VALVES BELOW SINKS AND	TOILETS ARE NOT OPERATED AS THEY ARE	Vent/fan	
Common cracks	Uamaged/locse baseboard/paneling App	parent damage Elections Full in	rical outlet detective Inspection obstructed Urnishings
Cracked/oroken tiles	Few/many vinyl tears/gouges Cup Major/minor carpet damage Loc	osa/uplifted tiles	
DOORS/ WINDOWS Windows: Outling pane appears fogged	Double hung Casement Sliding Door/window inoperative Mis	·	
DOORS/ WINDOWS Windows: Outling pane appears fogged	Double hung Casement Sliding Door/window inoperative Mis Door damaged/detaminated Evic	Flxed Othersing/damaged hardware	unters/cab:nots ocunters/cabiners ounters/cabiners ounters/cabiners oussing
DOORS/ WINDOWS Windows: Oual pane appears logged Cracked/broken glass FIXTURES/ CABINETS/ COUNTER Restricted vlow below sink Sink toose from wall/cabinet Sink cracked/chipped/damaged Corrosion or/under sink/drain Sink stainod/discolored Sink drains slowly Sink drain appears to leak Sink drain stopper inoperative	Double hung Casement Sliding Door/window inoperative Mis Door damaged/detaminated Evid Faucet futures corroded/leaking Tollet does not flush properly Tollet runs continually Totlet tank loose Cauking recommend around tollet base New toilet wax seal recommended Moisture evident around toilet Tollet bow/base cracked	Fixed Other sing/damaged hardware dence of leakage Toilet lank/cover crackedToilet seal loose/brokenkinor wear/damage to coKoderate wear/damage to coLatches/guides_need_adju	unters/cab:nots ocunters/cabiners ounters/cabiners ounters/cabiners oussing
DOORS/ WINDOWS Windows: Oual pand appears foggedCracked/broken glass FIXTURES/ CABINETS/ COUNTERRestricted viow below sinkSink toose from wall/cabinetSink cracked/chipped/damagedCorrosion or/under sink/drain	Double hung Casement Sliding Door/window inoperative Mis Door damaged/detaminated Evid Faucet futures corroded/leaking Tollet does not flush properly Tollet runs continually Totlet tank loose Cauking recommend around tollet base New toilet wax seal recommended Moisture evident around toilet Tollet bow/base cracked	Fixed Other sing/damaged hardware dence of leakage Toilet lank/cover crackedToilet seal loose/brokenkinor wear/damage to coKoderate wear/damage to coLatches/guides_need_adju	unters/cab:nots o counters/cab:nots ounters/cab:nots ounters/cab:nots ounters/cab:nots ounters/cab:nots ounters/cab:nots ounters/cab:nots ounters/cab:nots/cab:nots/cab:nots ounters/cab:nots/ca

· .

٠.

BATHROOMMAS	Cocation)		ANN	W O A E
COMMENTS			CRN	RF
ME SINK	DRAIN LESKS	Celling	18	
IN THE SI	B AREA	Walls	X	
		Doors	X	-
THE FLOUR I	INDER LAYMENT	Floor		LY
APPEARS MUI	STURE DAMAGE	Windows	X	
FROM LASK	AGE AT THE	Tollet/sinks		
- SHOWER EN	CUSURE	Tub/shower		
		Ventian		
Ceillea V D	ETS ARE NOT OPERATED AS THEY ARE PRO SS OF SHOWER PANS, ETC. IS NOT WITHIN TH YME!! Plaster Acoustic spray	NE TO LEAK DUE TO HARD W.	ATER AND LA	СК
Common cracks Appa	Inywall Plaster Acoustic spray Inywall Plaster Walipaper Panel rent moisture stains Apparen aged/locae baseboard/paneling Apparen GFC/'s	t damage Electricate Full insp	al outlet defecti section obstructionshings	
Unever/sloped Few/ Cracked/broken tiles Majo	many vinyl tazrs/gouges Cupping	ybuckling wood 💹 Apparei	nt moisture dar	กลดอ
DOORS/ WINDOWS Windows: Dual pane appears legged Door.	Double hung Cazement XSliding Missing/ damaged/delaminated Evidence	Fixed Other	······································	
DODRS/WINDOWS Windows: Dual pane appears fogged Door Cracked/broken glass Door Door CABINETS/ COUNTERS Restricted vlow below sink	Double hung Cazement Sliding Missing Missing damaged/delaminated Evidenc Faucet futures corroded/leaking	Fixed Other	inenVrapar	
DOORS/WINDOWS Windows:	Double hung Cazement	Fixed Other	inenVrapar	
DOORS/WINDOWS Windows:	Double hung Cazement	Fixed Other	dets/cab:nots ounters/cabinot niets/cabinets sing inent/repair nd counter and counter	overage and
DOORS/WINDOWS Windows: Dual pane appears fegged Door Cracked/broken glass Door Door Cracked/broken glass Door Door FIXTURES/ CABINETS/ COUNTERS Restricted vlow below sink	Double hung Cazement	Fixed Other damaged hardware e of leakage Toilet tank/cover cracked Toilet soat loose/broken Minor wear/damage to count Moderate wear/damage to count Heavy wear/damage to count Cabinet handles/factives mis Latches/guides need adjust Grouvcauking needed aroun Apparent shower pan leak Shower door difficult to oper Unable to determine if tempe Caulk/grout needed on show	dets/cab:nots ounters/cabinot niets/cabinets sing inent/repair nd counter and counter	

• .•

PLUMBING	A N N M P C P I A E
THE DISCHARGE DIPE TO THE WATER HEATER APR VALVE IS MISSING THE WATER HEATER IS NOT PROPERLY BRACED FOR EARTH QUAKE AP	Water Pipes Orain Pipes Vent Pipes Laundry Tub Tub Pump Pressure Water Heater Exhaus!
WATER SOURCE: SEWAGE SERVICE: WATER SERVICE ON: PUBLIC PRIVATE PRIVATE NO	Relief Valve
WATER MAIN/PIPES MAIN: Galvanized ***XCopper PVC; Other: PIPES: Galvanized ***XCopper PVC; Other: PIPES: Some/most piumbing concealed Water hammer noted Hopper Pvc; Other: Pv	
DRAIN/VENT PIPES Cast iron Galvanized Lead Plastic Un Some/most plumbing concealed Cracked pipe Moduratumeavy corresion noted No/negative fall No apparent/squeried floor drain	determinad pparent laaks o accessable cleanouts
LAUNDRY FACILITIES Location:	icets with shutaff valves
11 GARAGE 40GA GAS 10 YA Soperated as they are pr	Heater maccessable instore utilities or light pilots. Inspections with very limited. TPR valves and drains are not rone to leak following testing. The remaining after cannot be predictive.
Apparent leak noted Rust flakes on/around burner A Gas valve missing/inaccessible Nn TPR valve installed C	pparent insufficient ventilation ccess cover missing orrosion on connectors opper/flexible gas supply line

TO SECURE A PROPERTY OF THE PR

	ANNM
	CRNR
Service	X
Main panel	
Sub panels	1 X
Ground	
Wiring	
GFI's	
Smoke detector	
o main breaker de advised Corrosion noted at terminals dissing paget screws	Breakers 16
udditional GFI outlets recomme GFI outlet defective	
COLOUR IC WHILL DETURNANT BOS	Drillia Descozetius
Exposed wiring	· · · · · · · · · · · · · · · ·
ring is old, easily damaged an For these reasons we recom	
CTED THROUGHOUT TH ESSABLE TO THE INSPEC FORM FOR THE ROOM V	CTOR. ANY
	Main panel Sub panels Ground Winng GFI's Smoke detector cled at time of inspection Service lines too clo Serv

COMMENTS					C C	PIRN	A
			·	Operation			
				Draft Control	V	'	,
			_	Exhaust Sys			
				Distribution	∇		
				Fuel tank/line	s V		
				Thermostat	Ÿ		
				Blower	V		
	·			Humidifier	-^	V	
UTILITIES/PILO	OTS OFF AT TIME OF INSPECT	TION		Heat exchan	ger V		
Inspector does not re	estore utility service and does no	ot light pilots. Inspec	tions with utilities or	Relief Valve	-	X	
P 0.10 011 00 101 1 11111	ited. The inspector cannot defin be accomplished by dismantling	idivahi dalam ham a	xchanger cracks and	Circulator pu	mp	$\hat{\mathbf{x}}$	
EATING		y u ~ eyepenii.		Air Condition		3	
	LOCATION	TYPE	FUEL	APPROX BTUs	APPROX AGE		SIGI FE
SYSTEM # 1	INTERIOR	FURLES	GAS	90,000	4040	12	0
SYSTEM #2				7000	1,9 //	 -	
			l .		\$	1	
SYSTEM # 3 Unit fully/partially Pilot not in/not te Does not respon	osted App and to controls Ma	ctronic ignition math parent improper inst kee excessive/unus	allation ual noise	_ Closed unit/unable to ii _ Unusual flame partern _ Flame fluctuales when	observed fan comes on		
Unit fully/partially Pilot not in/not te Does not respor Darnaged/inope	posted Applied	parent improper inst kee excessive/unus icommend clean an parent backventing	allation ual noise d check	Unusual flame pattern Flame fluctuates when Rust flakes in combust Moderate/excessive or	orrosion on veni		erter
Unit fully/partially Pilot not in/not to Does not respon Darnaged/inoper ENTING/COMBUST Flue vent fully/pa Inadequate vent	Apple of the controls of the control of the	parent improper inst kee excessive/unus icommend clean an	allation ual noise d check noted yent installation Disposable act corrosion	Unusual flame partern Flame fluctuates when Rust flakes in combust	observed I fan comes on Jon chamber orrosion on vent ombustion air air		erter
Unit fully/partially Pilot not In/not te Does not respon Darnaged/inope ENTING/COMBUST Flue vent fully/pa Inadequate vent in ISTRIBUTION SYS Ducts largely co Damaged/discon	Apple of the controls of the c	parent improper institute excessive/unus icommend clean an parent backventing parent improper flue TER:Electror iderate/excessive diditional strapping releaks at joints	allation ual noise d check noted vent installation uct corrosion commended	Unusual flame pattern Flame fluctuates when Rust flakes in combust Moderate/excessive or Apparent insufficient or Missing/damaged regularity	observed I fan comes on Ion chamber orrosion on vent ombustion air air		erter
Unit fully/partially Pilot not in/not to Pilot not in/not to Poes not respon Darnaged/inopen ENTING/COMBUST Flue vent fully/pa Inadequate vent ISTRIBUTION SYS Ducts largely co Damaged/discon Apparent low air	Apple of the controls of the c	parent improper institute excessive/unus icommend clean an parent backventing parent improper flue TER:Electror iderate/excessive diditional strapping releaks at joints	allation ual noise d check noted vent installation uct corrosion commended	Unusual flame pattern Flame fluctuates when Rust flakes in combust Moderate/excessive co Apparent insufficient co Missing/damaged regs Missing/damaged fiter	observed I fan comes on Ion chamber orrosion on vent ombustion air air ster grill roper size filter Clip	DE	SIGI
Unit fully/partially Pilot not in/not to Done not respon Darnaged/inopen ENTING/COMBUST Five vent fully/pa Inadequate vent ISTRIBUTION SYS Ducts largely co Damaged/discount Apparent low air	App Maintenance Ma	parent improper institute excessive/unus icommend clean an icommend clean an icommend backventing parent backventing parent improper flue. TER:Electron iconsiste didional strapping reliable at joints T BE OPERATED, C	allation ual noise d check noted vent installation id	Unusual flame pattern Flame fluctuates when Rust flakes in combust Moderate/excessive of Apparent insufficient of Missing/damaged regulations Missing/damaged finer Missing/damaged finer	observed I fan comes on Ion chamber orrosion on vent ombustion air air ster grill roper size filter clip APPROX AGE	DE	
Unit fully/partially Pilot not in/not to Pilot not in/not to Does not respon Darnaged/inopen ENTING/COMBUST Flue vent fully/pa Inadequate vent ISTRIBUTION SYS Ducts largely co Damaged/discon Apparent low air	Apple of the controls of the c	parent improper institute excessive/unus icommend clean an icommend clean an icommend backventing parent backventing parent improper flue. TER:Electron iconsiste didional strapping reliable at joints T BE OPERATED, C	allation ual noise d check noted vent installation Disposable act corrosion commended PUTSIDE TEMPERAT	Unusual flame pattern Flame fluctuates when Rust flakes in combust Moderate/excessive of Apparent insufficient of Missing/damaged regulation Missing/damaged finer Missing/damaged finer Missing/damaged finer Missing/damaged finer TURE WAS TOO LOW APPROX BTUS	observed I fan comes on Ion chamber orrosion on vent ombustion air air ster grill roper size filter Clip	DE	SIGI

FOUNDATIONSTRUCTURE			A	14	14	86	G
* OBSIGENTO			C	P	l N	A	۶. د
COMMENTS					-2	aaa	13 (190)
		Foundation	X	-			-
		Beams	₹				
		Bearing Walls	*		c quantry		
	THE PERSONS WHEN STREET, STREE	Joists/Trusses	X			_	ua ș
		Piers/Posts	A	1		·····	n-va
		Floor/Slab	X	-			 ,
		Sump/Sump Pum	- -	X			
		Heat	l	V			on special
OUNDATION				•			
BASENIENT CRAW	L SPACE	SLAB					
None/partial None/partial None/partial None/partial	ORDINAL SALES	X None/partial/g	ഹ≪ശ (My			
CommonMarger:racks	o/blocked access	Large cracks	A.A				
	erks blocked	Unavan/slope					
The state of the s	pozreni moisture/no vapor b rete ineocessabia/concessa		eus co	v 84 6≪7	I		
TRUCTURE X Wood frame _ Sied frame _ B		Other					
IDISTURE EVIDENCE/CONTROL	xcessive floor sloping vidence of ehimening/repair		paga (Adapater Andria		-		
######################################		Sump ритр ж	ો.	iVolor			
Evidence of engoing foundation water penetration can easily be contained been to dry period prior to the inspection, evidence of past and the penetration and past and the penetration can easily be contained been to dry period prior to the inspection, evidence of past and the penetration can easily be contained been to dry period prior to the inspection, evidence of past and the penetration can easily be contained by the period prior to the inspection, evidence of past and the penetration can expect the penetration can easily be contained by the penetration can expend by the penetration can easily be contained by the penetration can expend by the penetration c	urno pump installed	y of uninflammonally by a normal occ	-4				⊕
Linest splanes cured missing possulptors COISTURE EVIDENCE/CONTROL. Evidence of ongoing water persystion Evidence of ongoing foundation water penetration can easily be contained been in dry period prior to the inspection, evidence of past and the inspection, evidence of past and the inspection, evidence of past and inspection of the inspection of past and inspec	urno pump installed	y or unintentionally by a horne occ visible or dissociable.	-4	Furt	ned, n		e C
Evidence of orgoing water pensysteion Evidence of orgoing foundation water ponetration can easily be contained been to dry period prior to the inspection, evidence of past and the pensysteion and past and the inspection, evidence of past and the inspection, evidence of past and the inspection and past and the inspection and the past and the inspection and the past and the inspection are inspection.	ump pump installed oncealed, either intentionally	y or unintentionally by a horne occ visible or dissociable.	upan.	Furi	Treat of the second	Ins	C
Literate plane counted missing possulpters COISTURE EVIDENCE CONTROL Evidence of ongoing water pensystion Evidence of engoing foundation water penetration can easily be contained been in the period prior to the inspection, evidence of past with the process of past with the pensystem.	urno pump installed	y or unintentionally by a horne occ visible or dissociable.	A C	Funi	N	inse isi A	0
Evidence of orgoing water pensysteion Evidence of orgoing foundation water ponetration can easily be contained been to dry period prior to the inspection, evidence of past and the pensysteion and past and the inspection, evidence of past and the inspection, evidence of past and the inspection and past and the inspection and the past and the inspection and the past and the inspection are inspection.	ump pump installed oncealed, either intentionally	y or unintermonally by a home occ visible or detectable.	A C	Funi	N	inse isi A	0
Evidence of orgoing water pensysteion Evidence of orgoing foundation water ponetration can easily be contained been to dry period prior to the inspection, evidence of past and the pensysteion and past and the inspection, evidence of past and the inspection, evidence of past and the inspection and past and the inspection and the past and the inspection and the past and the inspection are inspection.	ump pump installed oncealed, either intentionally	y or unintentionally by a horne occ visible or dissectable. Extenor Disors	A C	Funi	N	inse isi A	0
Evidence of orgoing water pensysteion Evidence of orgoing foundation water pensysteion can easily be come been to dry period prior to the inspection, evidence of past and the pensysteion can easily be come been to dry period prior to the inspection, evidence of past and the pensysteion can easily be compared to the inspection, evidence of past and the pensysteion can easily be compared to the inspection, evidence of past and the pensysteion can easily be compared to the inspection, evidence of past and the pensysteion can easily be compared to the inspection, evidence of past and the pensysteion can easily be compared to the pensysteion can easily be	ump pump installed oncealed, either intentionally	y or unintertonally by a home occ visible or descrapte. Extenor Doors Interior Doors Entryway	A C	Funi	N	inse isi A	0
Evidence of orgoing water pensysteion Evidence of orgoing foundation water pensysteion can easily be come been to dry period prior to the inspection, evidence of past and the pensysteion can easily be come been to dry period prior to the inspection, evidence of past and the pensysteion can easily be compared to the inspection, evidence of past and the pensysteion can easily be compared to the inspection, evidence of past and the pensysteion can easily be compared to the inspection, evidence of past and the pensysteion can easily be compared to the inspection, evidence of past and the pensysteion can easily be compared to the pensysteion can easily be	ump pump installed oncealed, either intentionally	Extenor Dixors Intenor Doors Entryway Starts	A C	Funi	N	inse isi A	0
Linest to the second wiseing presuptions List to the second or an angular persupsion Evidence of organing foundation water penetration can easily be come been in the period prior to the inspection, evidence of pear with the penetration of the pear with the inspection, evidence of pear with the inspection, evidence of pear with the penetration of the p	ump pump installed oncealed, either intentionally	y or unintertonally by a home occ visible or descrapte. Extenor Doors Interior Doors Entryway	A C	Funi	N	inse isi A	0
Linear splane consideration possibles CONTROL Lividence of organing water personation Enterescence Evidence of organing foundation water penetration can easily be contained been in dry period prior to the inspection, evidence of pear with the penetration of the pear with the inspection of the pear with the inspection of the pear with the penetration of the penetra	ump pump installed oncealed, either intentionally	Extenor Dixors Intenor Doors Entryway Starts	A C	Funi	N	inse isi A	C
Linear Commission of Personal Commission Can easily be commission of Com	ump pump installed on: concealed, either intentionally	Extenor Dixors Intenor Doors Entryway Starts	A C	Funi	N	inse isi A	C
Literate government and preservation Evidence of ongoing water penetration can easily be contained the inspection, evidence of pear with the inspection of the	ump pump installed on: concealed, either intentionally	Extenor Dixors Intenor Doors Entryway Starts	A C	Funi	N	inse isi A	0

ATTIC		CPIA
COMMENTS		CRNR
	Framing	
	Sheathing	
	Ventilation	- X - -
	Attic fan	
	Whole house fa	
	Insulation	_ LX
EVIDENCE OF ONGOING WATER PENETRATION?yes	time of inspection?	
VENTILATION/ ATTIC FAN/ WHOLE HOUSE FAN No/minimal ventilation Torn/missing vent screens Vents blocked Dryer/ exhaust fans vented into attic	Fan inoperative Fan is slow/noisy	and the second s
Uneven distribution/partially missing No moisture harrier a		
	pparem	to latitude
GARAGE	pparem	A N N M C P I A
GARAGE COMMENTS	pparem	
GARAGE	Door	CPIA
GARAGE		CPIA
GARAGE	Door	CPIA
GARAGE	Door Door opener	CPIA
GARAGE	Door Door opener Ceiling/walls	CPIA
GARAGE COMMENTS DOGR/DOGR OPENER Metal Wood/composite Other	Door Door opener Ceiling/walls Floor Condition	C P I A C R N R
GARAGE COMMENTS DOOR/DOOR OPENER Automatic opener/vesno; Operates properly (including the composition of the	Door Door opener Ceiling/walls Floor Condition	C P I A C R N R
GARAGE COMMENTS DOGR/DOGR OPENER Metal Wood/composite Other	Door Door opener Ceiling/walls Floor Condition	C P I A C R N R
GARAGE COMMENTS DOOR/DOOR OPENER Automatic opener	Door Door opener Ceiling/walls Floor Condition g automatic reverse) Window	C P I A C R N R
GARAGE COMMENTS DOOR/DOOR OPENER Automatic opener	Door Door opener Ceiling/walls Floor Condition Window Full ins Outlet	C P I A R N R
GARAGE COMMENTS DOOR/DOOR OPENER Automatic opener	Door Door opener Ceiling/walls Floor Condition Window	C P I A C R N R Xyesno; cracked/damaged/miss spection obstructed damagod/defective
GARAGE COMMENTS DOOR/DOOR OPENER Altomatic opener Yesno; Operates properly (includin	Door Door opener Ceiling/walls Floor Condition Window — Window — Full inc. — Outlet	C P I A C R N R Xyesno; cracked/damaged/miss spection obstructed damagod/defective
GARAGE COMMENTS DOOR/DOOR OPENER Automatic opener	Door Door opener Ceiling/walls Floor Condition Window — Window — Full inc. — Outlet	C P I A C R N R Xyesno; cracked/damaged/miss spection obstructed damagod/defective