

PAUL E. JONES NAPI CERT. # 30667

P.O. BOX 981071 W. SACRAMENTO, CA 95798 (916) 752-0275 e-mail: pjones21@comcast.net

DocuSigned by:

6/28/2022 | 9:12 PM PDT

Theresa M. Thorbur 6/29/2022 | 10:00 PM PDT = 28212C8CF9C4412...

INSPECTION DATE: June 24, 2022

REPORT NUMBER: A61271

CLIENT: Theresa & Keith Thorburn

PROPERTY INSPECTED: 512 Vieira St

Rio Vista, CA 94571

The property inspected is a 4 bedroom, 2 bath single family home. The weather at the commencement of the inspection was clear with a temperature reading of approximately 94 degrees Fahrenheit.

COMMENTS

The home is well constructed, structurally sound and nicely designed. Many of the suggested repairs are the result of normal wear.

Our evaluation is visual in nature of readily accessible areas. Excavation, lifting of floor coverings, opening walls or ceilings, moving furniture, personal or stored items, disassembly of equipment, or other potentially damaging or dangerous procedures were not performed. We do not specifically inspect for compliance with any building codes or regulations of any governmental or nongovernmental body or entity. Our review does not take into consideration the normal wear associated with virtually all properties.

INSPECTION SUMMARY

FOUNDATION SYSTEM

The foundation is a slab-on-grade foundation constructed of poured concrete. No evidence of excessive stress or settling to the foundation system was detected.

The foundation system is in an acceptable condition. No needed repairs to the foundation system were detected at the time of the inspection.

FRAMING STRUCTURE

The framing structure appears firm and intact within all accessible areas. The interior/exterior walls are plumb and square within acceptable ranges.

The framing structure is in an acceptable condition. No needed repairs to the framing structure were detected at the time of the inspection.

ROOF SYSTEM

Our evaluation of the roof is to determine if portions are missing and/or deteriorating and, therefore, subject to possible leaking. Portions of underlayment and decking are hidden from view and cannot be evaluated by our visual inspection; therefore, our review is not a guarantee against roof leaks nor a certification.

The roof surface is constructed of one layer of composition shingles. The estimated age of the roofing material is 23 years.

Maintenance issues:

1. The edges of several roofing shingles appear worn and the seams at the plumbing vent roof jacks appear poorly sealed (as viewed from the roof eaves). Suggest the roof be further inspected by a licensed roofing contractor and be repaired as found needed. (See Photo #1 and Photo #2)

ATTIC LEVEL

The attic framing structure is firm and intact. The attic area is adequately ventilated and well insulated with a polystyrene loose fill insulating material.

The attic level is in an acceptable condition. No needed repairs to the attic level were detected at the time of the inspection.

PLUMBING SYSTEM

The water supply and sewage system are public. The water supply lines are copper and the drain, waste and vent pipes are ABS. The water pressure appeared adequate at the time of the inspection.

The plumbing system is in an acceptable condition. No needed repairs to the plumbing system were detected at the time of the inspection.

ELECTRICAL SYSTEM

The electrical system is a 125 AMP service with solar panels. The service entrance panel is located at the South exterior. Overload protection is provided by circuit breakers.

No evidence of overheating or corrosion to the electrical system was detected. The size of the electrical system appears adequate.

The electrical system is in an acceptable condition. No needed repairs to the electrical system were detected at the time of the inspection.

WINDOWS

Maintenance issues:

 Condensation stains were noted between the glass panes of the sliding window at the master bathroom from an apparent failed vacuum seal. Suggest the glass panes be replaced by a licensed window contractor. (Stationary Side, See Photo #3)

NOTE

We wish to remind you that every house requires a certain amount of ongoing maintenance and this house is no exception. Drains sometimes clog, furnaces, air conditioners, water heaters all need periodic servicing and at some point in time may need to be replaced. These are but a few examples of things you can expect as a homeowner. It is suggested that you expect and budget for ongoing maintenance and repairs.

Please read the inspection worksheet for additional findings and recommendations.

Paul E. Jones





PHOTO #1 PHOTO #2



PHOTO #3

CODES: ACC - Acceptable, NPR - not present, NIN - not inspected, MAR - marginal, DEF - defective

				-	W. (************************************
LOTS & GROUNDS		•			
			N I	M	0
COMMENTS		C	P I R I	A A	E
		1	~+'	-	+-1
	Walks	X	+	┽	+{
	Steps Driveways	V	X -	十	1
	Fences	V	+	+-	1-1
	Retaining walls	1	-	+-	T
	Grading	()	_	†	11
	Swales	1	V	1	\forall
	Stairwell drain		*	+	17
	Window wells		V	1	T
	Surface drain	V	*	T	
	<u></u>	A			
WALKSAsphaltConcreteBrickGravel Other					
Common Cracks Large Cracks Heaving/settling Trip hazards Asphalt or					
					_
STEPS NA Concrete Wood Metal Brick Other					•
Earth to wood contact noted Apparent moisture damage Damaged/loos					
The same of the sa	ettisserry nei orais				
					-
DRIVEWAYAsphaltConcreteBrickGravel Other					
Common cracks Large cracks Heaving/settling Trip hazards Potholes noted Poor drainage Asphalt eroded Recommend					
Potholes noted Poor drainage Asphalt eroded Recommand	tealam				
					-
FENCESChain link	ther				
Few/many loose rotted posts Few/many missing/loose boards Wrought iron r	isted/corroded				
Loose/cracked/missing blocks Gate needs adjustment/repair Apparent moss	mariveact gamage				
					•
RETAINING WALLS Concrete Block Timbor Stone Masonry					
Common cracks Common displacement No weep holes Large cracks Large displacement Moisture dama	evident No	t plumb			
					•
SURFACE WATER CONTROL					
Grade slopes toward foundation Poor drainage apparent Earth to wood	contact Fa	nity grac	ling a	DD-21 BM	M.
					-
					_

ROOF						A	N P	N I	M A	D E
COMMENTS				r		<u>c</u>	R	N	R	F
COMMENTS	/_	- A			Roofing # 1	_ -				X
THE!	EDUEN OF	· 5E	NE/Y	<u> </u>	Roofing # 2		X			
1400F1	NO SHINGL	(E) /	APPEA	R_ !	Roofing # 3		X			
WURN A	IND THE SI	GAM	5" 197"		Roofing # 4		Ŷ			
THE DL	UMBING V	ENT	12001		Flashing					Y
JACKS	ADDEAR I	DUUR	LY		Skylights		V			A
SEALE	0'				Chimneys	_ \	1/3			
	-				Gutters	_ \$				
					Downspouts					
EVIDENCE OF LEAKS O	BLE" IS BASED ON THE AGE AND OR MAY SOON DEVELOP LEAKS. WITHIN THE LIMITS OF ITS AGE	HOWEVER	, SUCH A ROOF	CAN BE REP	AIRED AND GIVE	GENERA	LLY		SIGN	
	MATERIAL/LOCATION	LAYERS	INSPE	CTION ME	THOD	APPHO			FE.	
ROOFING # 1	COMPOSITION	V]	walked on _	Xladder at e	avesground	237	RE	3	رن	1
ROOFING # 2	77177		walked on	ladder at e	aves ground		1			_
ROOFING #3			walked on _	ladder at e	avesground		_			_
ROOFING #4			walked on	ladder at e	avesground					
Missing shakes/shing Ceteriorated granule Bare spots Spongy in areas FLASHINGS/VALLEYS No visible flashing	Many Pitch/s Evider	/cracked tiles blisters slope substar nce of leaks ent improper	installation	Crac Recc Rool deb	ping/curling iking/alligatoring parmend trimming partially obscured pris/snow/vegetation	t by solar p	aneis		flash	
SKYLIGHTS Apparent improper	N/A installation Craci	ked/daniaged	d glass	Evid	lence of leaks					
CHIMNEYS Bric Recommend recaul Recommend cap/s Missing/dateriorated	park arroster Appa	Other		Sep.	aration from struct appears unlined	ura				
GUTTERS, DOWNSPO Loose gutters/down Damaged gutters/d Evidence of loaks	reports Gutte ownsports Gutte	neut imbrobe ers zaöðind ersjaewusbor		Gutt	ierate/excessive c ler/downspout mis axtensions/splash	sing				

EXTERIOR SURFACE				
				A N N M D
COMMENTS				C P I A E
			Siding # 1	
			Siding # 2	V
			Windows	3
			Soffits/Fascia	Q
			Exterior Doors	3
			Shutters/Awnings	7
SIDING MATERIAL: Siding #1 LOCATION: Common Cracks Large/unusual cracks	Apparent moisture damage Damaged/loose siding	Touch up/ove	#3erall painting recommes	nded
Evidence of patching SOFFITS, FASCIAS, TRIM Damaged/loose/missing	Poor earth-to-wood clearance Wood Vinyl Metal; Othe Apparent moisture damage	Full inspectio	n obscured by vegetat	
PORCHES, DECKS, P	ATIOS			ANNMD
COMMENTS				CRNRF
			Porches	
			Decks	^Y
			Patios	\sigma_3 \qu
			Balconies	
PORCHES Apparent settling Apparent roof leaks	Loose support posts/pillars/railings Poor earth-to-wood-clearance	Apparent d	amaged flooring amage	
	No/low ci Apparent damage Popped nail Poor earth-to-wood clearance Apparent cr	s/loose boards	ed/could not fully inspe Not boited to house structural members	
PATIOS Concrete Brid	ck Flagstone Tile Other Lifting/settling Tripp	ing hazard	Sloped toward ho	Covered/could not inspe
BALCONIES NA				

TCHEN			IAININIMI
MMENTS			C P I A C R N A
		Ceiling/wal	ils
		Floor	S
		Doors/wind	Jows awot
		Sink/cabine	ets
		Appliances	
		Disposal	
		Dishwashe	. 8
		Ventilator	
		Built-ins	
Common cracks A Large/unusual cracks C	rywall Plaster Acoustic spray Prywall Plaster Wallpaper Apparent moisture stains Damaged/loose baseboard/paneling Sheet vinyl Wood Ceram	Apparent damage Apparent patching	Outlet/switch appears dete Full inspection obstructed
Uneven/sloped F Cracked/broken tiles N ORS/ WINDOWS Windows: Dual pane appears togged D	ew/many vinyl tears/gouges Aajor/minor carpet damage Double hung Casement Si	Cupping/bucking wood Loose/uplifted tiles	Full inspection obstructed Spongy/bouncy
Uneven/sloped F Cracked/broken tiles N ORS/ WINDOWS Windows: Dual pane appears togged D	ew/many vinyl tears/gouges Aajor/minor carpet damage Double hung Casement Si	Cupping/bucking wood Loose/uplifted tiles liding Fixed Other Missing/damaged hardware	Eull inspection obstructed Spongy/bouncy
Uneven/sloped FCracked/broken tiles N ORS/ WINDOWS Windows: Dual pane appears togged D Cracked/broken glass D	ew/many vinyl tears/gouges Aajor/minor carpet damage Double hung Casement Si	Cupping/bucking wood Loose/uplifted tiles liding Fixed Other Missing/damaged hardware	Full inspection obstructed Spongy/bouncy ars/cabinats unters/cabinats ars/cabinats ars/cabinats ars/cabinats ars/cabinats ars/cabinats ars/cabinats
Uneven/sloped F Cracked/broken tiles N ORS/ WINDOWS Windows: Dual pane appears fogged Cracked/broken glass D IK/ CABINETS/ COUNTERS Restricted view below sink Sink loose from wall/cabinot Sink cracked/chipped/damaged Corrosion on/uniter sink/drain Sink stained/discolored	ew/many vinyl tears/gouges Aajor/minor carpet damage Double hung Casement SI Door/window inoperative Door damaged/delaminated Sink hot and cold reversed Sink drain appears to leak Sink drain stopper inoperative Sink/drain improperly installed Faucet leaks	Cupping/bucking wood Loose/uplifted tiles liding Fixed Other Missing/damaged hardware Evidence of leakage Minor wear/damage to counte Moderate wear/damage to count Heavy wear/damage to count Cabinet handles/latches missi Latches/guides need adjustm	Full inspection obstructed Spongy/bouncy ars/cabinats unters/cabinats ars/cabinats ars/cabinats ars/cabinats ars/cabinats
Uneven/sloped F Cracked/broken tiles N ORS/ WINDOWS Windows: Dual pane appears togged Cracked/broken glass C IK/ CABINETS/ COUNTERS Restricted view below sink Sink loose from wall/cabinet Sink cracked/chipped/damaged Corrosion on/uniter sink/drain Sink stained/discolored Sink drains slowly	ew/many vinyl tears/gouges Aajor/minor carpet damage Double hung Casement Si Door/window inoperative Door damaged/delaminated Sink hot and cold reversed	Cupping/bucking wood Loose/uplifted tiles liding Fixed Other Missing/damaged hardware Evidence of leakage Minor wear/damage to counte Moderate wear/damage to count Heavy wear/damage to count Cabinet handles/latches missi Latches/guides need adjustm Grout/caulking needed around	Full inspection obstructed Spongy/bouncy ers/cabinets unters/cabinets iers/cabinets ing nent/repair d counter

ROOM LIVING ROOM (Location)	A N N M D C P I A E C R N R F
COMMENTS	
	Ceiling
THE CEILING IS PATCHED	Walls
FROM ADDARENT COM	Doors/Windows X
SEATLING AND IS NUT A	Floor
CUNCERN (INFORMATION ONLY)	Fireplace/etc.
	Outlets/switches
CEILING/.WALLS Ceiling: Drywall Plaster Acoustic spray Other Walls: Drywall Plaster Wallpaper Paneling Other Apparent moisture stains Apparent data Large/unusual cracks Damaged/loose baseboard/paneling Apparent par	mana Outles/switch appears defective
FLOOR Carpet Vinyl tile Sheet vinyl Wood Ceramic tile Uneven/šloped Few/many vinyl tears/gouges Cupping/but	Other Apparent moisture demage
Cracked/broken tiles Major/minor carpet damage Loose/uplift. DOORS/ WINDOWS Windows: Double hung CasementXSlidingXFixed	Other
	laged hardware leakage
ROOM MASTER BEDROOM (Location)	A N N M D C P L A E C R N R E
COMMENTS	
	Ceiling
ONE WINDOW SCREEN	Walls
15 MISS ING	Doors
	Floor
	Windows
	Outlets/switches
CEILING/ WALLS Ceiling - Drywall Plaster Acoustic spray Other Drywall Plaster Wallpaper Paneling Common cracks Apparent moisture stains Apparent Carge/unusual cracks Damaged/loose baseboard/paneling Apparent	AtherOutlet/switch appears defective
	Other Duckling wood Apparent moisture damage inted tiles
DOORS/ WINDOWS Windows: Double hung Casement X Sliding Fix	
	amaged hardware of leakage

ROOM SW BEDRUUM	A N N M D C P I A E
COMMENTS	CRNRF
	Ceiling
CLUSET DOURS NOT	Walls
PRESENT	Doors/Windows C
	Floor
	Fireplace/etc.
	Outlets/switches
CEILING/WALLS Walls:Orywall Plaster Wallpaper Paneling Of	her
Common cracksApparent moisture stainsApparentApparentApparentApparentApparentApparentApparentApparentApparentApparentApparentApparentApparentApparentApparentApparentApparentApparentApparentApparentApparentApparentApparentApparentApparentApparentApparentApparentApparentApparentApparentApparentApparentApparentApparentApparentApparentApparent	
FLOOR	Other
CECON Output VIII/I UND VIII/I VIII/I UND	
Unever/slopedFew/many vinyl tears/gougesCupping/tCracked/broken tilesMajor/minor carpet damageLoose/up	bucking wood Apparent mosture damage
DOORS/ WINDOWS Windows: Double hung Casement Sliding Fixe	old Other
	amaged hardware
Cracked/broken glass Door damaged/detaminated Evidence	of leakage
ROOM SULTH CENTER BEDI	CPIAE
COMMENTS	CRNA F
	Ceiling
CLUSET DOORS NOT	Walls
DRESENT	Doors
	Floor
	Windows
	Outlets/switches
CEILING/ WALLS Ceiling - Drywall Plaster Acoustic spray Other Walls - Drywall Plaster Wallpaper Paneling	Other
	nt damage Oullet/switch appears defective
FLOOR Carpet Vinyl tile Sheet vinyl Wood Ceramic tile	Other
	g/buckling wood Apparent mosture damage uplifted tiles
DOORS/ WINDOWS Windows: Double hung CasementSliding F	Fixed Other
Oual pane appears togged Door/window inoperative Missing	
Cracked/oroken glazsDoor damaged/delaminatedEviden	g/damaged hardware ce of leakage

ROOM SE BEDROOM	A N N M D C P I A E
COMMENTS	CRNRF
	Ceiling
CLUST TOORS NOT	Walls
- PICESENT	Doors/Windows 2
	Floor
	Fireplace/etc.
	Outlets/switches
CEILING/.WALLS Ceiling: Drywall Plaster Acoustic agray Ott Plaster Wallpaper Paneling Ott Pl	samage Outlet/switch appears defective
FLOOR Carpet Vinyl tile Sheet vinyl Wood Ceramic tile Unevervisioped Few/many vinyl tears/gouges Cupping/b Cracked/broken tiles Major/minor carpet damage Loose/upl	
DOORS/ WINDOWS Windows:Double hungCasementSlidingFixeDual pane appears foggedDoor/window inoperativeMissing/daCracked/broken glassDoor damaged/delaminatedEvidence	amaged hardware
ROOM LAUNDRY ROUM	A N N M D C P I A E C R N R F
COMMENTS	
)	
	Ceiting
	Walls
	Walls Doors
	Walls
	Walls Doors
	Walis Doors Floor
CEILING/ WALLS Ceiling - Drywall Plaster Acoustic spray Other Walls - Drywall Plaster Wallpaper Paneling	Walls Doors Floor Windows Outlets/switches
CEILING/ WALLS Ceiling - Drywall Plaster Acoustic spray Other Walls - Plaster Wallpaper Paneling Common cracks Apparent moisture stains Apparent Large/unusual cracks Damaged/loose baseboard/paneling Apparent	Walls Doors Floor Windows Outlets/switches Other Other Other Outlets/switches
WallsOnywellPlaster Wallpaper Paneling Common cracks Apparent moisture stains Apparent Large/unusual cracks Darnaged/loose baseboard/paneling Apparent FLOOR Carpet Vinyl tile Sheet vinyl Wood Ceramic tile	Walls Doors Floor Windows Outlets/switches Other Outlets/switches Other Outlets/switches Other Outlets/switches Other Outlets/switches Other Outlets/switches Outlets/switches
Walls - Orywall Plaster Wallpaper Paneling Common cracks	Walls Doors Floor Windows Outlets/switches Other It damage
Walls - Drywall Plaster Wallpaper Paneling Common cracksApparent moisture stainsApparent	Walls Doors Floor Windows Outlets/switches Other It damage Outlevswitch appears defective It patching Full inspection obstructed by furnishings Other Outlevswitch appears defective Apparent moisture damage uplified tiles

(Location)	A]	n	N]:	u į	о ¦
COMMENTS	C	P	N I	1	E
Ceiling	X				
Walls	X		+	-	-
Doors	X	\dashv	+	\dashv	\dashv
Floor	\forall	\dashv	-	}	
Windows	C	X	+	-	\dashv
Toilet/sinks	X	\dashv	\dashv	-	\dashv
Tub/shower Vent/fan	X	+	-	-	\dashv
SUPPLY VALVES BELOW SINKS AND TOILETS ARE NOT OPERATED AS THEY ARE PRONE TO LEAK DUE TO HARD WAT OF USE. DETERMINING WATERTIGHTNESS OF SHOWER PANS, ETC. IS NOT WITHIN THE SCOPE OF THIS INSPECTION CEILING/ WALLS Ceiling Drywall Plaster Acoustic spray Other Drywall Plaster Wallpaper Paneling Other Other	ľ				المسيية
Common cracks Apparent moisture stains Apparent damage Electrical of Large/unusual cracks Damaged/loose baseboard/paneling Apparent patching Full inspec GFCI's not present by furnish	ction	obeti			
FLOOR Carpet Vinyl tile Shoet vinyl Wood Ceramic tile Other Cupping/buckling wood Apparent to Cracked/broken tiles Major/minor carpet damage Loose/uplifted tiles	morsi	ture (dama	ge 	
Door/window inoperative					
FIXTURES/ CABINETS/ COUNTERS					
Restricted viow below sink Sink loose from wall/cabinet Toilet does not flush properly Toilet seat loose/broken Toilet runs continually Minor wear/damage to counters Corrosion on/under sink/drain Toilet tank loose Moderate wear/damage to counter Sink stained/discolored Cauking recommend around toilet base Heavy wear/damage to counter Sink drains slowly New toilet wax seal recommended Cabinet handles/latches missin Sink drain appears to leak Moisture evident around toilet Latches/guides need adjustme Sink drain stopper inoperative Toilet bow/base cracked Grout/cauking needed around toilet Faucet has constant drop	nlers irs/ca ng anVre	vcabi Ibinel	neis		
TUB/SHOWER			.,,		
Damage/deterioration noted Mirror/excessive corrosion noted Caulking needed along base Faucet appears to leak Valves operate with difficulty Damage/deterioration noted Cracked/broken tiles noted Low water volume noted Constant dripping at spout Drain stopper inoperative Apparent slow draining Moisture damage at floor/wall Apparent shower pan leak Shower door difficult to operate Unable to determine if tempere Constant dripping at spout Caulk/grout needed on shower Whirlpool/jets not operative/ Whirlpool/jets not operative/ Apparent slow draining	od gla 1 wall				
VENT/FAN		•			•
No exhaust fan Fan noisy/slow Supplemental heater installed Fan not operational Heat provided by central system Heater appears defective/inop	orato	ve			

COMMITME	NMD
Walls GASS GASS	I A E
SUPPLY VALVES BELOW SINKS AND TOILETS ARE NOT OPERATED AS THEY ARE PRONE TO LEAK DUE TO HARD WATER AND LACK OF USE. DETERMINING WATERTIGHTINESS OF SHOWER PANS, ETC. IS NOT WITHIN THE SCOPE OF THIS INSPECTION CEILING/ WALLS Ceiling Drywall Plaster Acoustic spray Other Other Common cracks Apparent moisture stains Damaged/loose baseboard/paneling Apparent damage Electrical outlet defective Apparent patching Full inspection obstructed by furnishings FLOOR Carpet Vinyl tile Shoet vinyl Wood Ceramic tile Cupping/buckling wood Apparent moisture damage Cracked/broken tiles Major/minor carpet damage Loose/uplifted tiles	1-1-1
SUPPLY VALVES BELOW SINKS AND TOILETS ARE NOT OPERATED AS THEY ARE PRONE TO LEAK DUE TO HARD WATER AND LACK OF USE. DETERMINING WATERTIGHTNESS OF SHOWER PANS, ETC. IS NOT WITHIN THE SCOPE OF THIS INSPECTION CEILING/ WALLS Ceiling Drywall Plaster Acoustic spray Other Other Drywall Plaster Wallpaper Paneling Other Common cracks Apparent moisture stains Apparent damage Electrical outlet defective Large/unusual cracks Damaged/loose baseboard/paneling Apparent patching Full inspection obstructed by furnishings FLOOR Carpet Vinyl tile Shoet vinyl Wood Ceramic (ile Other Unever/sloped Few/many vinyl tears/gouges Cupping/buckling wood Apparent moisture damage Cracked/broken tiles Major/minor carpet damage Loose/uplifted tiles	
Windows Toilet/sinks Tub/shower Vent/tan SUPPLY VALVES BELOW SINKS AND TOILETS ARE NOT OPERATED AS THEY ARE PRONE TO LEAK DUE TO HARD WATER AND LACK OF USE. DETERMINING WATERTIGHTNESS OF SHOWER PANS, ETC. IS NOT WITHIN THE SCOPE OF THIS INSPECTION CEILING/ WALLS Ceiling Drywall Plaster Acoustic spray Other Drywall Plaster Wallpaper Paneling Other Common cracks Apparent moisture stains Apparent damage Electrical outlet defective Apparent patching Full inspection obstructed by furnishings FLOOR Carpet Vinyl tile Shoet vinyl Wood Ceramic tile Other Unever/sloped Few/many vinyl tears/gouges Cupping/buckling wood Apparent moisture damage Cracked/broken tiles Major/minor carpet damage Loose/uplifted tiles	
SUPPLY VALVES BELOW SINKS AND TOILETS ARE NOT OPERATED AS THEY ARE PRONE TO LEAK DUE TO HARD WATER AND LACK OF USE. DETERMINING WATERTIGHTNESS OF SHOWER PANS, ETC. IS NOT WITHIN THE SCOPE OF THIS INSPECTION CEILING/ WALLS Ceiling Drywall Plaster Acoustic spray Other Drywall Plaster Wallpaper Paneling Other Common cracks Apparent moisture stains Apparent damage Electrical outlet defective Large/unusual cracks Damaged/loose baseboard/paneling Apparent patching Full inspection obstructed by furnishings FLOOR Carpet Vinyl tile Shoet vinyl Wood Ceramic tile Other Uneven/sloped Few/many vinyl tears/gouges Cupping/buckling wood Apparent moisture damage Cracked/broken tiles Major/minor carpet damage Loose/uplifted tiles	
SUPPLY VALVES BELOW SINKS AND TOILETS ARE NOT OPERATED AS THEY ARE PRONE TO LEAK DUE TO HARD WATER AND LACK OF USE. DETERMINING WATERTIGHTNESS OF SHOWER PANS, ETC. IS NOT WITHIN THE SCOPE OF THIS INSPECTION CEILING/ WALLS Ceiling Drywall Plaster Acoustic spray Other Drywall Plaster Wallpaper Paneling Other Common cracks Apparent moisture stains Apparent damage Electrical outlet defective Large/unusual cracks Damaged/loose baseboard/paneling Apparent patching Full inspection obstructed by furnishings IFLOOR Carpet Vinyl tile Shoet vinyl Wood Ceramic (ile Other Unever/sloped Few/many vinyl tears/gouges Cupping/buckling wood Apparent moisture damage Cracked/broken tiles Major/minor carpet damage Loose/uplifted tiles	L X
SUPPLY VALVES BELOW SINKS AND TO/LETS ARE NOT OPERATED AS THEY ARE PRONE TO LEAK DUE TO HARD WATER AND LACK OF USE. DETERMINING WATERTIGHTNESS OF SHOWER PANS, ETC. IS NOT WITHIN THE SCOPE OF THIS INSPECTION CEILING/ WALLS Ceiling Drywall Plaster Acoustic spray Other Common cracks Apparent moisture stains Apparent damage Electrical outlet defective Large/unusual cracks Damaged/loose baseboard/paneling Apparent patching Full inspection obstructed by furnishings IFLOOR Carpet Vinyl tile Shoet vinyl Wood Ceramic (ile Other Uneverysloped Few/many vinyl tears/gouges Cupping/buckling wood Apparent moisture damage Cracked/broken tiles Major/minor carpet damage Loose/uplifted tiles	
SUPPLY VALVES BELOW SINKS AND TOILETS ARE NOT OPERATED AS THEY ARE PRONE TO LEAK DUE TO HARD WATER AND LACK OF USE. DETERMINING WATERTIGHTNESS OF SHOWER PANS, ETC. IS NOT WITHIN THE SCOPE OF THIS INSPECTION CEILING/ WALLS Ceiling Drywall Plaster Acoustic spray Other Common cracks Apparent moisture stains Apparent damage Electrical outlet defective Large/unusual cracks Damaged/loose baseboard/paneling Apparent patching Full inspection obstructed by furnishings FLOOR Carpet Vinyl tile Shoet vinyl Wood Ceramic (ile Other Uneven/sloped Few/many vinyl tears/gouges Cupping/buckling wood Apparent moisture damage Cracked/broken tiles Major/minor carpet damage Loose/uplifted tiles	1-1-1
OF USE. DETERMINING WATERTIGHTNESS OF SHOWER PANS, ETC. IS NOT WITHIN THE SCOPE OF THIS INSPECTION CEILING/ WALLS Ceiling Walls: Drywall Plaster Acoustic spray Other Drywall Plaster Wallpaper Paneling Other Common cracks Apparent moisture stains Apparent damage Electrical outlet defective Apparent patching Full inspection obstructed by furnishings GFCI's not present by furnishings FELOOR Carpet Vinyl tile Shoet vinyl Wood Ceramic tile Other Uneven/sloped Few/many vinyl tears/gouges Cupping/buckling wood Apparent moisture damage Cracked/broken tiles Major/minor carpet damage Loose/uplifted tiles	
Uneven/slopedFew/many vinyl tears/gouges Cupping/buckling wood Apparent moisture damage Cracked/broken tiles Major/minor carpet damage Loose/uplifted tiles	afactiva
Cracked/broken tiles Major/minor carpet damage Loose/uplifted tiles	-
DOORS/ WINDOWS Windows: Double hung CasementSliding Fixed Other	e damage
Dual pane appears fogged Door/window inoperative Missing/damaged hardware Evidence of leakage	
FIXTURES/ CABINETS/ COUNTERS	
Restricted view below sink Sink loose from wall/cabinet Sink cracked/chipped/damaged Corrosion on/under sink/drain Sink stained/discolored Sink drains slowly Sink drain appears to leak Sink drain stopper inoperative Sink/drain improperly installed Toilet text corroded/leaking Toilet text corroded/leaking Toilet text continually Minor wear/damage to counters/cabinets Moderate wear/damage to counters/cabinets Heavy wear/damage to counters/cabinets Cauking recommend around toilet base Sink drain appears to leak Moisture evident around toilet Sink/drain improperly installed Faucet has constant drop	ibneis isis
TUB/SHOWER	
Damage/deterioration noted Moisture damage at floor/wall Minor/excessive corrosion noted Caulking needed along base Faucet appears to leak Valves operate with difficulty Moisture damage at floor/wall Cracked/broken tiles noted Low water volume noted Low water volume noted Constant dripping at spout Drain stopper inoperative Apparent slow draining Moisture damage at floor/wall Apparent shower pan teak Shower door difficult to operate Unable to determine if tempered glass Caulk/grout needed on shower walls Whirlpool/jets not operative/ Apparent slow draining	
VENT/FAN	
No exhaust fanFan noisy/stowSupplemental heater installedFan not operationalHeat provided by central systemHeater appears defective/noperative	

PLUMBIN	NG									 A	N	N :	м	D
COMMENTS										C	P R	- 1	- (E
								Water Pip	es					
								Drain Pip	es					_
								Vent Pipe	25	3				
	,						_	Laundry		1			7	_
						****		Tub Pum				1		_
				·····			_	Pressure			X		\neg	_
							_	Water He	ater			1		
· · · · · · · · · · · · · · · · · · ·								Exhaust		X			7	-
							-	Relief Va	ive	3		_		
ATER SOUL	RCE:	PUBLIC PUBLIC YES		PRIVATE PRIVATE						**	-			_
ATER SER	AICE ON:	YES		NO										
RAIN/VENT Some/ Modera No app	most plumbing concealed and leaks noted corroded/inoperative PIPES most plumbing concealed ate/heavy corrosion noted plumbing concealed ate/heavy corrosion noted parent/covered floor drain	Cast iron	Water had Strapping Copper/g Copper/g Galvanize Cracked No/negat	mmer noted precommende alvanized cor ed Lea pipe pive fall	ed ntact not	Plastic _	Ho	se faucet dai se faucet not letermined parent leaks accessable	maged/iño i seif drain	oing	⊕lea •	king		
Foatures pr	ACILITIES Lor rces provided:Gas recent:/ Sink	cation:	Drain (9	220 volt	electric	/ <u>/</u>	/ater fauc	cels with shut	off valves					
Heater	TER	SIZE	FUEL	AGE	The	Pilot/electri			Heate				الدمها ح	•
#1		40 GA	. (-C)S	CUA				restore utilitie rery limited.	-					11
#2	GARAGE	10 07	- 545	073	-			one to leak fo aler cannot b	_		the r	กมงากน	เกฎ	
Appare	ent leak noted alve missing/inaccessible ged/corroded case.		_ No TPR _ Apparent	es on/around valvo installed t improper ins ve extension	l burner d stallation		Ap Ad Cd	pparent insuff scess cover r orrosion on co opper/flexible	ncient vent nissing onnectors	tilation				
nderland (Philaderna Philaderna)			-											

	JUAR PANEL			IAI	n l n	MI
COMMENTS				C	PI	A
			Service		1	
			Main panel	*	_	1 1
			Sub panels	7		
			Ground	不		
			Wiring	X		
			GFI's			
			Smoke detector	X		
Deteriorated weathernead connec Missing/loose/damaged weathern	aad Damaged/frayed		Service lines too		ind/veg	elælor
MAIN PANEL: SUBPANELS:	EXTERIOR	<u> </u>	at 1100 circuis	15	· · · · · · · · · · · · · · · · · · ·	
SERVICE SIZE: 125 AN	Size could not be determined					
		rent standards/upgrade a nce Corro s Missi		noted		
COPPER ALUMINUM Couble tapping noted Apparent overfusing Open ended uncapped wires	Appears outdated by curr No/insufficient panel clearer Unprotected panel openings Missing cover	rent standards/upgrade a nce Corro s Missi	dvised ision noted at terminals ng panel screws	noted		
COPPER ALUMINUM Couble tapping noted Apparent overfusing Open ended uncapped wires	Appears outdated by curr No/insufficient panel clearer Unprotected panel openings Missing cover	rent standards/upgrade a nceCorro aMissiScort eterAddriv sGFI c	dvised ision noted at terminals ng panel screws			
COPPER ALUMINUM Double tapping noted Apparent overfusing Open ended uncapped wires GROUNDING/GROUND FAULT IN' Ground rod/water line ground No apparent grounding system Loose clamp at rod/water line		eter Addrius GFI cont grounded	dvised ision noted at terminals ng panel screws ched/overheated wires ponal GFI outlets recomm utilet defective prevented view of impro	nended	1 wring	**************************************
COPPERALUMINUM Double tapping notedApparent overfusingOpen ended uncapped wires GROUNDING/GROUND FAULT INGround rod/water line groundNo apparent grounding systemLoose clamp at rod/water line WIRTING Branch wiring:Xcopp	No/insufficient panel clearer Unprotected panel openings Missing cover TERRUPTERS (GFI's) No bypass around water me Few/many two prong outlets 3 prong outlets apparently recommended and a panel openings or aluminium Damaged/corroded condust Junction box cover missing present unique safety concerns a specialty rated connecters and ins	eter Addrid s Curro	dvised son noted at terminals ng panel screws ched/overheated wires onal GFI outlets recomm outlet defective prevented view of impro sed wiring oper wiring s old, easily damaged a	mended ppur/exposes and may eve	ntually	
COPPER ALUMINUM Double tapping noted Apparent overfusing Open ended uncapped wires GROUNDING/GROUND FAULT IN Ground rod/water line ground No apparent grounding system Loose clamp at rod/water line MIRING	No/insufficient panel clearer Unprotected panel openings Missing cover TERRUPTERS (GFI's) No bypass around water m Few/many two prong outlets 3 prong outlets apparently r aluminium Damaged/corroded condust Junction box cover missing sing present unique safety concerns a specialty rated connecters and ins	eterAddition of the provided and prounded Furnishing/storage Expo	sion noted at terminals ag panel screws ched/overheated wires ched/overheated wires ched/overheated wires ched/overheated wires ched/overheated wires chedwing ched wiring cold, easily damaged at these reasons we reco	nended pur/exposed and may eve	ntually	
COPPERALUMINUM Double tapping notedApparent overfusingOpen ended uncapped wires GROUNDING/GROUND FAULT INGround rod/water line groundNo apparent grounding systemtoose clamp at rod/water line WIRING Branch wiring:Xcopp"knob and tube" wiring notedExposed wire/termination/splice Both "knob and tube" and aluminum wiring require	Appears outdated by curr No/insufficient panel clearer Unprotected panel openings Missing cover TERRUPTERS (GFI's) No bypass around water me Few/many two prong outlets 3 prong outlets apparently r aluminium Damaged/corroded condust Junction box cover missing iring present unique safety concerns a specially rated connecters and ins n. TRICAL OUTLETS AND SWITCH TS AND SWITCHES ARE NEC COVERED ARE NOTED ON The	eterAddition Furnishing/storage Expo Impressibility Expo Exp	existed soon noted at terminals repaired screws ched/overheated wires ched/overheated wi	nended opur/exposed and may eve immend an e	ntcally valuable	

HEATING							
COMMENTS						A N	I A E
TIL	FURNINCE	10/10	410	_I	0		NAF
	11/20/10/	14/1/2	14/606		Operation	— X -	+
Elinole	7 (10600	JAN T	VW-/45		Draft Control	X -	╅┼┼
11016	CVI CC	100 J	TOUGH	}	Exhaust Syste	<u>***</u>	+++
-FVAVIS	r d Coco		1E/X		Distribution	X -	╌┼╼┼╼
DESIG	3N LIPE	UNFO	ONLY)	Fuel tank/line	<u> </u>	+-+-
					Thermostat	X-	
					Blower	X	
					Humidifier		4
UTILITIES/PILOT	'S OFF AT TIME OF INSPECTI	ON			Heat exchange	er X	1
	store utility service and does not	•			Relief Valve		4-1-
	ed. The inspector cannot definiti be accomplished by dismantling t		changer cracks and		Circulator pur	ne	
HEATING					Air Conditioni	علال العد	
HEATING							
	LOCATION	TYPE	FUEL	AP	PROX BTUs	APPROX AGE	DESIGH LIFE
SYSTEM # 1	ATTIC	FURIFE	0 645	90	1,000	234R5	ZUYR
SYSTEM # 2							
SYSTEM #3							
Does not respon Damaged/inoper VENTING/COMBUST Tile vent fully/pai	Stive controls Rec Rec TON AIR Itially inaccessible App	es excessive/unus commend clean an arent backventing	d check _	Rue	ne fluctuates when t flakes in combust	orrasion on year	
Inadequate vant (arent improper flue		400	event insufficient c	ombudaudmo	
DISTRIBUTION SYS Ducts largely co Damaged/discoi Apparent low air	ncested Moo	TER:Electron derate/excessive di itional strapping re eaks at joints	commended	Mis	sing/damaged regi sing/damaged/imp sing/damaged fitei	coper size filter	
AIR CONDITIONING	COULD NOT	BE OPERATED,	OUTSIDE TEMPERA	TURE	WAS TOO LOW		
	LOCATION	TYPE	FUEL	Al	PPROX BTUs	APPROX AGE	DESIGN
SYSTEM # 1	WESTERIOR	CANTA!	EVELT		3-TON	23 yes	20 x
SYSTEM # 2							
Unit makes exc Visible damage	. —	ndenser airflow obs satisfactory temper	-		parent freon/conde taide unit not level	nsale line leaks	
				 			

FOUNDATION/STRUCTURE			
COMMENTS			A N N M D C P I A E C R N R F
		Foundation	
		Beams	
		Bearing Walls	
		Joists/Trusses	13
		Piers/Posts	
		Floor/Slab	
		Sump/Sump Pum	X
		Heat	
OUNDATION			
BASEMENT	CRAWL SPACE	(SUE)	
Nonu/partial BlockPoured concrete Brick Stone	None/partial No/blocked access	Common crac	
Commontarge cracks No vents		Large cracks	
	Vents blocked Apparent moisture/no vapor barri	unever/slope Smal/large ar	
Areas inaccessable/concealed/uninspecied	Areas inscressable/concented/u		
IOISTURE EVIDENCE/CONTROL Evidence of ongoing water penetration Efflorescence	Sump pump installed	Ѕытр рытр а	ppears inoperative
Evidence of engoing foundation water penetration can enhance to the inspection, evidence of the inspection of the inspec			Supant. Further, dishere
COMMENTS			C P I A E
		Extenor Doors	
		Intenor Doors	1011
		Entryway	
		Slaurs	
		Hallways	Na I
DOORS			_
entryway, Stairs, Hallways			·
		· · · · · · · · · · · · · · · · · · ·	

ATTIC		ANNMD
COMMENTS		CRNRE
	Framing	
	Sheathing	A
	Ventilation	\mathbf{X}
	Attic fan	X
	Whole house fan	X
	Insulation	
METHOD OF INSPECTION:None/no access,Complete access \(\subseteq \text{Limited acc} \) EVIDENCE OF ONGOING WATER PENETRATION?yes \(\subseteq \text{no, Location:} \) Water penetration can be conclusively determined only if it is raining at the time of inspection.		
FRAMING/ SHEATHING		
Cracked/broken/sagging structural member Evidence of mois Cracked/damaged/missing access panel	sture damage/dry rot/other damage	3
VENTILATION ATTIC FAN/ WHOLE HOUSE FAN		the Parish and Company of the Compa
No/minimal ventilation Torn/missing vent screens Vents blocked Dryer/ exhaust fans vented into attic	Fan inoperative Fan is slow/noisy	
GARAGE		A N N M D
COMMENTS		C P I A E
	Door	
	Door opener	\$
	Ceiling/walls	Z
	Floor	X
	Condition	X
DOOR/DOOR OPENER MetalWood/composite Other	(including automatic reverse) X	yesno;
Weather seal damaged/missingApparent damage/moisture damDoor appears out of adjustment/alignment		cked/damaged/missing
CEILING/WALLS Ceiling - Drywall Plaster Acoustic spray Other Walis - Drywall Plaster Paneling; Other:		
Common cracks Apparent moisture stains Apparent of Large/unusual cracks Damaged/loose trim Apparent p	damage Outlet dar	ction obstructed nagod/defective nt GFI protected
PEDESTRIAN DOOR/WINDOWS		
Windows:Double hungCasementSlidingFixed Other	e	
Damager/broken/inoperative window Damaged/inoperative door		
WINDOW NOT PRESO	ent	
FLCOR	· · · · · · · · · · · · · · · · · · ·	
Common cracks Large/unusual cracks F	leaving/settling	
·		