



PAUL E. JONES
NAPI CERT. # 30667

P.O. BOX 981071
W. SACRAMENTO, CA 95798
(916) 752-0275
e-mail: pjones21@comcast.net

DocuSigned by:

Betty J. Boudreaux 10/23/2023 | 10:38 PM PDT

E33CB040E6F5476...

INSPECTION DATE: October 19, 2023

REPORT NUMBER: A71211

CLIENT: Betty Jean Boudreaux

PROPERTY INSPECTED: 3600 Thompson Ct
Fairfield, CA 94534

The property inspected is a 4 bedroom, 2.5 bath single family home. The weather at the commencement of the inspection was clear with a temperature reading of approximately 79 degrees Fahrenheit.

COMMENTS

The home is nicely designed, well constructed and structurally sound. Many of the suggested repairs are the result of normal wear.

Our evaluation is visual in nature of readily accessible areas. Excavation, lifting of floor coverings, opening walls or ceilings, moving furniture, personal or stored items, disassembly of equipment, or other potentially damaging or dangerous procedures were not performed. We do not specifically inspect for compliance with any building codes or regulations of any governmental or non-governmental body or entity. Our review does not take into consideration the normal wear associated with virtually all properties.

INSPECTION SUMMARY

FOUNDATION SYSTEM

The foundation is an above grade foundation (pier & beam). The foundation walls are constructed of poured concrete. No evidence of excessive stress or settling to the foundation system was detected.

The foundation system is in an acceptable condition. No needed repairs to the foundation system were detected at the time of the inspection.

FRAMING STRUCTURE

The framing structure appears firm and intact within all accessible areas. The interior/exterior walls are plumb and square within acceptable ranges.

The framing structure is in an acceptable condition. No needed repairs to the framing structure were detected at the time of the inspection.

ROOF SYSTEM

Our evaluation of the roof is to determine if portions are missing and/or deteriorating and, therefore, subject to possible leaking. Portions of underlayment and decking are hidden from view and cannot be evaluated by our visual inspection; therefore, our review is not a guarantee against roof leaks nor a certification.

The roof surface is constructed of composition shingles. The estimated age of the roofing material is 15 to 20 years.

Maintenance issues:

1. A few roofing shingles at the garage roof cover appear damaged and the seams at the plumbing vent jacks appear poorly sealed. Suggest the roof be further inspected by a licensed roofing contractor and be repaired as found needed. (See Photo #1 and Photo #2)

ATTIC LEVEL

The attic framing structure is firm and intact. The attic area is adequately ventilated and well insulated with a cellulose loose fill insulating material.

The attic level is in an acceptable condition. No needed repairs to the attic level were detected at the time of the inspection.

ELECTRICAL SYSTEM

The electrical system is a 200 AMP service. The service entrance panel is located at the East exterior. Overload protection is provided by circuit breakers.

No evidence of overheating or corrosion to the electrical system was detected. The size of the electrical system appears adequate.

The electrical system is in an acceptable condition. No needed repairs to the electrical system were detected at the time of the inspection.

PLUMBING SYSTEM

The water supply and sewage system are public. The water supply lines are copper and drain, waste and vent pipes are ABS. The water pressure appeared adequate at the time of the inspection.

Maintenance issues:

1. The water main leaks above the gate valve. Suggest the water main be repaired by a qualified licensed contractor. (See Photo #3)

DOORS

Maintenance issues:

1. The exterior door between the kitchen and garage is not fire-rated. Suggest a fire-rated door be installed by a qualified licensed contractor to maintain a fire barrier between the garage and house interior. (Safety Concern, See Photo #4)
2. The door latch to the sliding glass door at the family room is broken and will not secure. Suggest the door latch assembly be replaced by a qualified licensed contractor. (See Photo #5)
3. The base of the water heater closet door drags on the floor and is difficult to open and close. Suggest the door be repaired by a qualified licensed contractor. (See Photo #6)

GARAGE

Maintenance issues:

1. An approximate 15" by 30" opening was noted in the drywall at the South wall of the garage interior exposing the wall cavity. Suggest the wall opening be sealed with fire-rated drywall by a qualified licensed contractor to maintain a fire barrier between the garage and house interior. (Safety Concern, See Photo #7)

LOTS & GROUNDS

Maintenance issues:

1. Sections of the concrete walkway at the front entry and near the South wall of the house are cracked and lifted from apparent common settling and/or tree roots. Suggest the walkways be repaired by a qualified licensed contractor. (Trip Hazard, See Photo #8)
2. Sections of the concrete patio near the garage is cracked and uneven from apparent common settling. Suggest the patio be repaired by a qualified licensed contractor. (Trip Hazard, See Photo #9)

NOTE

We wish to remind you that every house requires a certain amount of ongoing maintenance and this house is no exception. Drains sometimes clog, furnaces, air conditioners, water heaters all need periodic servicing and at some point in time may need to be replaced. These are but a few examples of things you can expect as a homeowner. It is suggested that you expect and budget for ongoing maintenance and repairs.

Please read the inspection worksheet for additional findings and recommendations.



Paul E. Jones



PHOTO #1



PHOTO #2



PHOTO #3



PHOTO #4



PHOTO #5



PHOTO #6



PHOTO #7



PHOTO #8



PHOTO #9

CODES: ACC - Acceptable, NPR - not present, NIN - not inspected, MAR - marginal, DEF - defective

LOTS & GROUNDS

COMMENTS

THE CONCRETE WALKWAY
AT THE FRONT ENTRY AND
SOUTH WALL OF THE HOUSE
ARE CRACKED AND UNEVEN

	A C C	N P R	N I N	M A R	D E F
Walks					X
Steps	X				
Driveways	X				
Fences	X				
Retaining walls		X			
Grading	X				
Swales		X			
Stairwell drain		X			
Window wells		X			
Surface drain	X				

WALKS ___ Asphalt Concrete ___ Brick ___ Gravel Other _____
 ___ Common Cracks ___ Large Cracks ___ Heaving/settling Trip hazards ___ Asphalt eroded in places

STEPS ___ Concrete Wood ___ Metal ___ Brick Other _____
 ___ Earth to wood contact noted ___ Apparent moisture damage ___ Damaged/loose/missing handrails

DRIVEWAY ___ Asphalt Concrete ___ Brick ___ Gravel Other _____
 ___ Common cracks ___ Large cracks ___ Heaving/settling ___ Trip hazards
 ___ Potholes noted ___ Poor drainage ___ Asphalt eroded ___ Recommend sealant

FENCES Chain link Wood ___ Wire ___ Wrought iron ___ Masonry Other _____
 ___ Few/many loose rotted posts ___ Few/many missing/loose boards ___ Wrought iron rusted/corroded
 ___ Loose/cracked/missing blocks ___ Gate needs adjustment/repair ___ Apparent moisture/insult damage

RETAINING WALLS ___ Concrete ___ Block ___ Timber ___ Stone ___ Masonry Other _____
 ___ Common cracks ___ Common displacement ___ No weep holes evident ___ Not plumb
 ___ Large cracks ___ Large displacement ___ Moisture damage

N/A

SURFACE WATER CONTROL
 ___ Grade slopes toward foundation ___ Poor drainage apparent ___ Earth to wood contact ___ Faulty grading apparent

EXTERIOR SURFACE

COMMENTS

Siding # 1	X				
Siding # 2		X			
Windows	X				
Soffits/Fascia	X				X
Exterior Doors	X				
Shutters/Awnings		X			

A	N	N	M	D
C	P	I	A	E
C	R	N	R	F

SIDING

MATERIAL: Siding #1 WOOD SIDINGS Siding #2 _____ Siding #3 _____

LOCATION: _____

- Common Cracks
- Large/unusual cracks
- Evidence of patching
- Apparent moisture damage
- Damaged/loose siding
- Poor earth-to-wood clearance
- Touch up/overall painting recommended
- Patching holes/cracks/gaps recommended
- Full inspection obscured by vegetation/other

SOFFITS, FASCIAS, TRIM

Wood Vinyl Metal; Other: _____

- Damaged/loose/missing
- Apparent moisture damage
- Poor earth-to-wood clearance

PORCHES, DECKS, PATIOS

COMMENTS

THE CONCRETE PATIO
NEAR THE EAST WALL OF
THE GARAGE IS CRACKED
AND UNEVEN

Porches	X			
Decks		X		
Patios				X
Balconies		X		

A	N	N	M	D
C	P	I	A	E
C	R	N	R	F

PORCHES

- Apparent settling
- Apparent roof leaks
- Loose support posts/pillars/railings
- Poor earth-to-wood-clearance
- Apparent damaged flooring
- Apparent damage

DECKS

NIA

No/low clearance/surface covered/could not fully inspect

- No footings evident
- Loose/missing handrails
- Apparent damage
- Poor earth-to-wood clearance
- Popped nails/loose boards
- Apparent cracked/broken/sagging structural members
- Not bolted to house
- No joist hangers

PATIOS

- Concrete Brick Flagstone Tile Other _____
- Common/large cracks
- Lifting/settling
- Tripping hazard
- Covered/could not inspect
- Sloped toward house

BALCONIES

NIA

- Loose/missing handrail
- Apparent damage
- Sagging/loose floor
- Apparently not bolted to house
- No joist hangers

KITCHEN

COMMENTS

THE EXTERIOR DOOR IS NOT FIRE-RATED

	A	N	N	M	D
	C	P	I	A	E
	C	R	N	R	F
Ceiling/walls	<input checked="" type="checkbox"/>				
Floor	<input checked="" type="checkbox"/>				
Doors/windows					<input checked="" type="checkbox"/>
Sink/cabinets	<input checked="" type="checkbox"/>				
Appliances	<input checked="" type="checkbox"/>				
Disposal	<input checked="" type="checkbox"/>				
Dishwasher	<input checked="" type="checkbox"/>				
Ventilator	<input checked="" type="checkbox"/>				
Built-ins		<input checked="" type="checkbox"/>			

CEILING/ WALLS

Ceiling: Drywall ___ Plaster ___ Acoustic spray ___ Other _____
 Walls: Drywall ___ Plaster ___ Wallpaper ___ Paneling ___ Other _____

- Common cracks
- Large/unusual cracks
- Apparent moisture stains
- Damaged/loose baseboard/paneling
- Apparent damage
- Apparent patching
- Outlet/switch appears defective
- Full inspection obstructed

FLOOR

___ Carpet ___ Vinyl tile ___ Sheet vinyl ___ Wood ___ Ceramic tile

Other **LUXURY VINYL PLANK**

- Uneven/sloped
- Cracked/broken tiles
- Few/many vinyl tears/gouges
- Major/minor carpet damage
- Cupping/bucking wood
- Loose/uplifted tiles
- Full inspection obstructed
- Spongy/bouncy

DOORS/ WINDOWS

Windows: Double hung ___ Casement ___ Sliding ___ Fixed ___ Other _____

- Dual pane appears fogged
- Cracked/broken glass
- Door/window inoperative
- Door damaged/delaminated
- Missing/damaged hardware
- Evidence of leakage

SINK/ CABINETS/ COUNTERS

- Restricted view below sink
- Sink loose from wall/cabinet
- Sink cracked/chipped/damaged
- Corrosion on/under sink/drain
- Sink stained/dischlored
- Sink drains slowly
- Sink hot and cold reversed
- Faucet fixtures corroded
- Sink drain appears to leak
- Sink drain stopper inoperative
- Sink/drain improperly installed
- Faucet leaks
- Faucet has constant drip
- Minor wear/damage to counters/cabinets
- Moderate wear/damage to counters/cabinets
- Heavy wear/damage to counters/cabinets
- Cabinet handles/latches missing
- Latches/guides need adjustment/repair
- Grout/caulking needed around counter

APPLIANCES/ BUILT-INS

- RANGE/COOKTOP ___ None ___ Not tested ___ Operational
- OVEN ___ None ___ Not tested ___ Operational
- DISHWASHER ___ None ___ Not tested ___ Operational
- GARBAGE DISPOSAL ___ None ___ Not tested ___ Operational
- MICROWAVE None ___ Not tested ___ Operational
- TRASH COMPACTOR None ___ Not tested ___ Operational

VENTILATION

- No hood/fan installed
- Fan noisy/slow
- Fan inoperative

ROOM FAMILY ROOM
(Location)

A	N	N	M	D
C	P	I	A	E
C	R	N	R	F

COMMENTS
THE DOOR LATCH TO THE SLIDING GLASS DOOR WILL NOT SECURE

Ceiling	X				
Walls	X				
Doors/Windows					X
Floor	X				
Fireplace/etc.	X				
Outlets/switches	X				

CEILING/WALLS
Ceiling: Drywall ___ Plaster ___ Acoustic spray ___ Other _____
Walls: Drywall ___ Plaster ___ Wallpaper ___ Paneling ___ Other _____

___ Common cracks ___ Apparent moisture stains ___ Apparent damage ___ Outlet/switch appears defective
___ Large/unusual cracks ___ Damaged/loose baseboard/paneling ___ Apparent patching ___ Full inspection obstructed by furnishings

FLOOR Carpet ___ Vinyl tile ___ Sheet vinyl ___ Wood ___ Ceramic tile ___ Other _____

___ Uneven/sloped ___ Few/many vinyl tears/gouges ___ Cupping/buckling wood ___ Apparent moisture damage
___ Cracked/broken tiles ___ Major/minor carpet damage ___ Loose/uplifted tiles

DOORS/ WINDOWS Windows: ___ Double hung ___ Casement ___ Sliding ___ Fixed Other SLIDING GLASS DOOR

___ Dual pane appears fogged ___ Door/window inoperative ___ Missing/damaged hardware ___ Evidence of leakage
___ Cracked/broken glass ___ Door damaged/delaminated

ROOM LIVING ROOM
(Location)

A	N	N	M	D
C	P	I	A	E
C	R	N	R	F

COMMENTS

Ceiling	X				
Walls	X				
Doors		X			
Floor	X				
Windows	X				
Outlets/switches	X				

CEILING/WALLS
Ceiling: Drywall ___ Plaster ___ Acoustic spray ___ Other _____
Walls: Drywall ___ Plaster ___ Wallpaper ___ Paneling ___ Other _____

___ Common cracks ___ Apparent moisture stains ___ Apparent damage ___ Outlet/switch appears defective
___ Large/unusual cracks ___ Damaged/loose baseboard/paneling ___ Apparent patching ___ Full inspection obstructed by furnishings

FLOOR Carpet ___ Vinyl tile ___ Sheet vinyl ___ Wood ___ Ceramic tile ___ Other _____

___ Uneven/sloped ___ Few/many vinyl tears/gouges ___ Cupping/buckling wood ___ Apparent moisture damage
___ Cracked/broken tiles ___ Major/minor carpet damage ___ Loose/uplifted tiles

DOORS/ WINDOWS Windows: Double hung ___ Casement ___ Sliding ___ Fixed Other _____

___ Dual pane appears fogged ___ Door/window inoperative ___ Missing/damaged hardware ___ Evidence of leakage
___ Cracked/broken glass ___ Door damaged/delaminated

ROOM FORMAL DINING ROOM
(Location)

A	N	N	M	D
C	P	I	A	E
C	R	N	R	F

COMMENTS

Ceiling	X				
Walls	X				
Doors/Windows	X				
Floor	X				
Fireplace/etc.		X			
Outlets/switches	X				

CEILING/WALLS Ceiling: Drywall ___ Plaster ___ Acoustic spray ___ Other _____
Walls: Drywall ___ Plaster ___ Wallpaper ___ Paneling Other _____

___ Common cracks ___ Apparent moisture stains ___ Apparent damage ___ Outlet/switch appears defective
___ Large/unusual cracks ___ Damaged/loose baseboard/paneling ___ Apparent patching ___ Full inspection obstructed by furnishings

FLOOR ___ Carpet ___ Vinyl tile ___ Sheet vinyl ___ Wood ___ Ceramic tile Other LUXURY VINYL PLANK

___ Uneven/sloped ___ Few/many vinyl tears/gouges ___ Cupping/buckling wood ___ Apparent moisture damage
___ Cracked/broken tiles ___ Major/minor carpet damage ___ Loose/uplifted tiles

DOORS/ WINDOWS Windows: Double hung ___ Casement ___ Sliding ___ Fixed Other _____

___ Dual pane appears fogged ___ Door/window inoperative ___ Missing/damaged hardware
___ Cracked/broken glass ___ Door damaged/delaminated ___ Evidence of leakage

ROOM MASTER BEDROOM
(Location)

A	N	N	M	D
C	P	I	A	E
C	R	N	R	F

COMMENTS

Ceiling	X				
Walls	X				
Doors	X				
Floor	X				
Windows	X				
Outlets/switches	X				

CEILING/WALLS Ceiling: Drywall ___ Plaster ___ Acoustic spray ___ Other _____
Walls: Drywall ___ Plaster ___ Wallpaper ___ Paneling Other _____

___ Common cracks ___ Apparent moisture stains ___ Apparent damage ___ Outlet/switch appears defective
___ Large/unusual cracks ___ Damaged/loose baseboard/paneling ___ Apparent patching ___ Full inspection obstructed by furnishings

FLOOR Carpet ___ Vinyl tile ___ Sheet vinyl ___ Wood ___ Ceramic tile Other _____

___ Uneven/sloped ___ Few/many vinyl tears/gouges ___ Cupping/buckling wood ___ Apparent moisture damage
___ Cracked/broken tiles ___ Major/minor carpet damage ___ Loose/uplifted tiles

DOORS/ WINDOWS Windows: Double hung ___ Casement ___ Sliding ___ Fixed Other _____

___ Dual pane appears fogged ___ Door/window inoperative ___ Missing/damaged hardware
___ Cracked/broken glass ___ Door damaged/delaminated ___ Evidence of leakage

ROOM N.W. BEDROOM
(Location)

A	N	N	M	D
C	P	I	A	E
C	R	N	R	F

COMMENTS

Ceiling	<input checked="" type="checkbox"/>				
Walls	<input checked="" type="checkbox"/>				
Doors/Windows	<input checked="" type="checkbox"/>				
Floor	<input checked="" type="checkbox"/>				
Fireplace/etc.		<input checked="" type="checkbox"/>			
Outlets/switches	<input checked="" type="checkbox"/>				

CEILING/WALLS
 Ceiling: Drywall ___ Plaster ___ Acoustic spray ___ Other ___
 Walls: Drywall ___ Plaster ___ Wallpaper ___ Paneling ___ Other ___

___ Common cracks ___ Apparent moisture stains ___ Apparent damage ___ Outlet/switch appears defective
 ___ Large/unusual cracks ___ Damaged/loose baseboard/paneling ___ Apparent patching ___ Full inspection obstructed by furnishings

FLOOR Carpet ___ Vinyl tile ___ Sheet vinyl ___ Wood ___ Ceramic tile ___ Other ___

___ Uneven/sloped ___ Few/many vinyl tears/gouges ___ Cupping/buckling wood ___ Apparent moisture damage
 ___ Cracked/broken tiles ___ Major/minor carpet damage ___ Loose/uplifted tiles

DOORS/ WINDOWS Windows: Double hung ___ Casement ___ Sliding ___ Fixed ___ Other ___

___ Dual pane appears fogged ___ Door/window inoperative ___ Missing/damaged hardware
 ___ Cracked/broken glass ___ Door damaged/delaminated ___ Evidence of leakage

ROOM N.E. BEDROOM
(Location)

A	N	N	M	D
C	P	I	A	E
C	R	N	R	F

COMMENTS

Ceiling	<input checked="" type="checkbox"/>				
Walls	<input checked="" type="checkbox"/>				
Doors	<input checked="" type="checkbox"/>				
Floor	<input checked="" type="checkbox"/>				
Windows	<input checked="" type="checkbox"/>				
Outlets/switches	<input checked="" type="checkbox"/>				

CEILING/WALLS
 Ceiling: Drywall ___ Plaster ___ Acoustic spray ___ Other ___
 Walls: Drywall ___ Plaster ___ Wallpaper ___ Paneling ___ Other ___

___ Common cracks ___ Apparent moisture stains ___ Apparent damage ___ Outlet/switch appears defective
 ___ Large/unusual cracks ___ Damaged/loose baseboard/paneling ___ Apparent patching ___ Full inspection obstructed by furnishings

FLOOR Carpet ___ Vinyl tile ___ Sheet vinyl ___ Wood ___ Ceramic tile ___ Other ___

___ Uneven/sloped ___ Few/many vinyl tears/gouges ___ Cupping/buckling wood ___ Apparent moisture damage
 ___ Cracked/broken tiles ___ Major/minor carpet damage ___ Loose/uplifted tiles

DOORS/ WINDOWS Windows: Double hung ___ Casement ___ Sliding ___ Fixed ___ Other ___

___ Dual pane appears fogged ___ Door/window inoperative ___ Missing/damaged hardware
 ___ Cracked/broken glass ___ Door damaged/delaminated ___ Evidence of leakage

ROOM S.W. BEDROOM
(Location)

A	N	N	M	D
C	P	I	A	E
C	R	N	R	F

COMMENTS

Ceiling	<input checked="" type="checkbox"/>				
Walls	<input checked="" type="checkbox"/>				
Doors/Windows	<input checked="" type="checkbox"/>				
Floor	<input checked="" type="checkbox"/>				
Fireplace/etc.	<input checked="" type="checkbox"/>				
Outlets/switches	<input checked="" type="checkbox"/>				

CEILING/WALLS
 Ceiling: Drywall ___ Plaster ___ Acoustic spray ___ Other ___
 Walls: Drywall ___ Plaster ___ Wallpaper ___ Paneling ___ Other ___

___ Common cracks ___ Apparent moisture stains ___ Apparent damage ___ Outlet/switch appears defective
 ___ Large/unusual cracks ___ Damaged/loose baseboard/paneling ___ Apparent patching ___ Full inspection obstructed by furnishings

FLOOR ___ Carpet ___ Vinyl tile ___ Sheet vinyl Wood ___ Ceramic tile ___ Other ___

___ Uneven/sloped ___ Few/many vinyl tears/gouges ___ Cupping/buckling wood ___ Apparent moisture damage
 ___ Cracked/broken tiles ___ Major/minor carpet damage ___ Loose/uplifted tiles

DOORS/ WINDOWS Windows: Double hung ___ Casement ___ Sliding ___ Fixed ___ Other ___

___ Dual pane appears fogged ___ Door/window inoperative ___ Missing/damaged hardware
 ___ Cracked/broken glass ___ Door damaged/delaminated ___ Evidence of leakage

ROOM _____
(Location)

A	N	N	M	D
C	P	I	A	E
C	R	N	R	F

COMMENTS

Ceiling					
Walls					
Doors					
Floor					
Windows					
Outlets/switches					

CEILING/WALLS
 Ceiling - ___ Drywall ___ Plaster ___ Acoustic spray ___ Other ___
 Walls - ___ Drywall ___ Plaster ___ Wallpaper ___ Paneling ___ Other ___

___ Common cracks ___ Apparent moisture stains ___ Apparent damage ___ Outlet/switch appears defective
 ___ Large/unusual cracks ___ Damaged/loose baseboard/paneling ___ Apparent patching ___ Full inspection obstructed by furnishings

FLOOR ___ Carpet ___ Vinyl tile ___ Sheet vinyl ___ Wood ___ Ceramic tile ___ Other ___

___ Uneven/sloped ___ Few/many vinyl tears/gouges ___ Cupping/buckling wood ___ Apparent moisture damage
 ___ Cracked/broken tiles ___ Major/minor carpet damage ___ Loose/uplifted tiles

DOORS/ WINDOWS Windows: ___ Double hung ___ Casement ___ Sliding ___ Fixed ___ Other ___

___ Dual pane appears fogged ___ Door/window inoperative ___ Missing/damaged hardware
 ___ Cracked/broken glass ___ Door damaged/delaminated ___ Evidence of leakage

BATHROOM

HALF
(Location)

COMMENTS

	A	N	N	M	D
	C	P	I	A	E
	C	R	R	R	F
Ceiling	X				
Walls	X				
Doors	X				
Floor	X				
Windows	X				
Toilet/sinks	X				
Tub/shower		X			
Vent/fan			X		

SUPPLY VALVES BELOW SINKS AND TOILETS ARE NOT OPERATED AS THEY ARE PRONE TO LEAK DUE TO HARD WATER AND LACK OF USE. DETERMINING WATERTIGHTNESS OF SHOWER PANS, ETC. IS NOT WITHIN THE SCOPE OF THIS INSPECTION

CEILING/ WALLS Ceiling Drywall Plaster Acoustic spray Other _____
 Walls: Drywall Plaster Wallpaper Paneling Other _____

Common cracks Apparent moisture stains Apparent damage Electrical outlet defective
 Large/unusual cracks Damaged/loose baseboard/paneling Apparent patching Full inspection obstructed by furnishings
 GFCI's not present

FLOOR Carpet Vinyl tile Sheet vinyl Wood Ceramic tile Other TILE

Uneven/sloped Few/many vinyl tears/gouges Cupping/buckling wood Apparent moisture damage
 Cracked/broken tiles Major/minor carpet damage Loose/uplifted tiles

DOORS/ WINDOWS Windows: Double hung Casement Sliding Fixed Other _____

Dual pane appears fogged Door/window inoperative Missing/damaged hardware
 Cracked/broken glass Door damaged/delaminated Evidence of leakage

FIXTURES/ CABINETS/ COUNTERS

Restricted view below sink Faucet fixtures corroded/leaking Toilet tank/cover cracked
 Sink loose from wall/cabinet Toilet does not flush properly Toilet seat loose/broken
 Sink cracked/chipped/damaged Toilet runs continually Minor wear/damage to counters/cabinets
 Corrosion on/under sink/drain Toilet tank loose Moderate wear/damage to counters/cabinets
 Sink stained/discolored Caulking recommend around toilet base Heavy wear/damage to counters/cabinets
 Sink drains slowly New toilet wax seal recommended Cabinet handles/latches missing
 Sink drain appears to leak Moisture evident around toilet Latches/guides need adjustment/repair
 Sink drain stopper inoperative Toilet bowl/base cracked Grou/caulking needed around counter
 Sink/drain improperly installed Faucet has constant drop

TUB/SHOWER

Damage/deterioration noted Moisture damage at floor/wall Apparent shower pan leak
 Minor/excessive corrosion noted Cracked/broken tiles noted Shower door difficult to operate
 Caulking needed along base Low water volume noted Unable to determine if tempered glass
 Faucet appears to leak Constant dripping at spout Caulk/grout needed on shower walls
 Valves operate with difficulty Drain stopper inoperative Whirlpool/jets not operative/tested
 Apparent slow draining

VENT/FAN

No exhaust fan Fan noisy/slow Supplemental heater installed
 Fan not operational Heat provided by central system Heater appears defective/inoperative

BATHROOM

MASTER

(Location)

COMMENTS

	A	N	N	M	D
	C	P	I	A	E
	C	R	N	R	F
Ceiling	X				
Walls	X				
Doors	X				
Floor	X				
Windows	X				
Toilet/sinks	X				
Tub/shower	X				
Vent/fan	X				

SUPPLY VALVES BELOW SINKS AND TOILETS ARE NOT OPERATED AS THEY ARE PRONE TO LEAK DUE TO HARD WATER AND LACK OF USE. DETERMINING WATERTIGHTNESS OF SHOWER PANS, ETC. IS NOT WITHIN THE SCOPE OF THIS INSPECTION

CEILING/ WALLS Ceiling Drywall Plaster Acoustic spray Other _____
 Walls: Drywall Plaster Wallpaper Paneling Other _____

- Common cracks
- Large/unusual cracks
- Apparent moisture stains
- Damaged/loose baseboard/paneling
- Apparent damage
- Apparent patching
- GFCI's not present
- Electrical outlet defective
- Full inspection obstructed by furnishings

FLOOR Carpet Vinyl tile Sheet vinyl Wood Ceramic tile Other TILE

- Uneven/sloped
- Cracked/broken tiles
- Few/many vinyl tears/gouges
- Major/minor carpet damage
- Cupping/buckling wood
- Loose/uplifted tiles
- Apparent moisture damage

DOORS/ WINDOWS Windows: Double hung Casement Sliding Fixed Other _____

- Dual pane appears fogged
- Cracked/broken glass
- Door/window inoperative
- Door damaged/delaminated
- Missing/damaged hardware
- Evidence of leakage

WINDOW NOT PRESENT

FIXTURES/ CABINETS/ COUNTERS

- Restricted view below sink
- Sink loose from wall/cabinet
- Sink cracked/chipped/damaged
- Corrosion on/under sink/drain
- Sink stained/discolored
- Sink drains slowly
- Sink drain appears to leak
- Sink drain stopper inoperative
- Sink/drain improperly installed
- Faucet fixtures corroded/leaking
- Toilet does not flush properly
- Toilet runs continually
- Toilet tank loose
- Caulking recommend around toilet base
- New toilet wax seal recommended
- Moisture evident around toilet
- Toilet bowl/base cracked
- Faucet has constant drop
- Toilet tank/cover cracked
- Toilet seal loose/broken
- Minor wear/damage to counters/cabinets
- Moderate wear/damage to counters/cabinets
- Heavy wear/damage to counters/cabinets
- Cabinet handles/latches missing
- Latches/guides need adjustment/repair
- Grout/caulking needed around counter

TUB/SHOWER

- Damage/deterioration noted
- Minor/excessive corrosion noted
- Caulking needed along base
- Faucet appears to leak
- Valves operate with difficulty
- Moisture damage at floor/wall
- Cracked/broken tiles noted
- Low water volume noted
- Constant dripping at spout
- Drain stopper inoperative
- Apparent slow draining
- Apparent shower pan leak
- Shower door difficult to operate
- Unable to determine if tempered glass
- Caulk/grout needed on shower walls
- Whirlpool/jets not operative/tested

VENT/FAN

- No exhaust fan
- Fan not operational
- Fan noisy/slow
- Heat provided by central system
- Supplemental heater installed
- Heater appears defective/inoperative

BATHROOM

UPPER LEVEL HALL
(Location)

COMMENTS

THE BATHING TRIP -
LEVER DRAIN STOPPER IS
INOPERABLE AND A RUBBER
DRAIN COVER IS IN USE.
(INFORMATION ONLY)

	A	N	N	M	D
	C	P	I	A	E
	C	R	N	R	F
Ceiling	X				
Walls	X				
Doors	X				
Floor	X				
Windows	X				
Toilet/sinks	X				
Tub/shower	X				
Vent/fan					X

SUPPLY VALVES BELOW SINKS AND TOILETS ARE NOT OPERATED AS THEY ARE PRONE TO LEAK DUE TO HARD WATER AND LACK OF USE. DETERMINING WATERTIGHTNESS OF SHOWER PANS, ETC. IS NOT WITHIN THE SCOPE OF THIS INSPECTION

CEILING/ WALLS Ceiling Drywall Plaster Acoustic spray Other _____
Walls: Drywall Plaster Wallpaper Paneling Other _____

- Common cracks
- Large/unusual cracks
- Apparent moisture stains
- Damaged/loose baseboard/paneling
- Apparent damage
- Apparent patching
- GFCI's not present
- Electrical outlet defective
- Full inspection obstructed by furnishings

FLOOR Carpet Vinyl tile Sheet vinyl Wood Ceramic tile Other TILE

- Uneven/sloped
- Cracked/broken tiles
- Few/many vinyl tears/gouges
- Major/minor carpet damage
- Cupping/buckling wood
- Loose/uplifted tiles
- Apparent moisture damage

DOORS/ WINDOWS Windows: Double hung Casement Sliding Fixed Other _____

- Dual pane appears fogged
- Cracked/broken glass
- Door/window inoperative
- Door damaged/delaminated
- Missing/damaged hardware
- Evidence of leakage

FIXTURES/ CABINETS/ COUNTERS

- Restricted view below sink
- Sink loose from wall/cabinet
- Sink cracked/chipped/damaged
- Corrosion on/under sink/drain
- Sink stained/discolored
- Sink drains slowly
- Sink drain appears to leak
- Sink drain stopper inoperative
- Sink/drain improperly installed
- Faucet fixtures corroded/leaking
- Toilet does not flush properly
- Toilet runs continually
- Toilet tank loose
- Caulking recommend around toilet base
- New toilet wax seal recommended
- Moisture evident around toilet
- Toilet bowl/base cracked
- Faucet has constant drop
- Toilet tank/cover cracked
- Toilet seat loose/broken
- Minor wear/damage to counters/cabinets
- Moderate wear/damage to counters/cabinets
- Heavy wear/damage to counters/cabinets
- Cabinet handles/latches missing
- Latches/guides need adjustment/repair
- Grout/caulking needed around counter

TUB/SHOWER

- Damage/deterioration noted
- Mirror/excessive corrosion noted
- Caulking needed along base
- Faucet appears to leak
- Valves operate with difficulty
- Moisture damage at floor/wall
- Cracked/broken tiles noted
- Low water volume noted
- Constant dripping at spout
- Drain stopper inoperative
- Apparent slow draining
- Apparent shower pan leak
- Shower door difficult to operate
- Unable to determine if tempered glass
- Caulk/grout needed on shower walls
- Whirlpool/jets not operative/tested

VENT/FAN

- No exhaust fan
- Fan not operational
- Fan noisy/slow
- Heat provided by central system
- Supplemental heater installed
- Heater appears defective/inoperative

ELECTRICAL

COMMENTS

Service					
Main panel	X				
Sub panels	X				
Ground	X				
Wiring	X				
GFI's	X				
Smoke detector	X				

A	N	N	M	D
C	P	I	A	E
C	R	N	R	F

SERVICE

Overhead Underground

Service disconnected at time of inspection

- Deteriorated weatherhead connections
- Missing/loose/damaged weatherhead

- Loose/leaning mast
- Damaged/trayed drip loops

- Service lines too close to roof
- Service lines too close to ground/vegetation

PANELS

LOCATION

of 220V circuits

of 110V circuits

Breakers

MAIN PANEL:
SUB PANELS:

EAST EXTERIOR

4

15

19

SERVICE SIZE:

200 AMP

Size could not be determined with certainty/no main breaker

COPPER ALUMINUM

Appears outdated by current standards/upgrade advised

- Double tapping noted
- Apparent overfusing
- Open ended uncapped wires

- No/insufficient panel clearance
- Unprotected panel openings
- Missing cover

- Corrosion noted at terminals
- Missing panel screws
- Scorching/overheated wires noted

GROUNDING/GROUND FAULT INTERRUPTERS (GFI's)

- Ground rod/water line ground
- No apparent grounding system
- Loose clamp at rod/water line
- No bypass around water meter
- Few/many two prong outlets
- 3 prong outlets apparently not grounded
- Additional GFI outlets recommended
- GFI outlet defective

WIRING

Branch wiring: copper aluminum

Furnishing/storage prevented view of improper/exposed wiring

- "knob and tube" wiring noted
- Exposed wire/termination/splice
- Damaged/corroded conduits
- Junction box cover missing
- Exposed wiring
- Improper wiring

Both "knob and tube" and aluminum wiring present unique safety concerns. "Knob and tub" wiring is old, easily damaged and may eventually need replacement. Aluminum wiring requires specially rated connectors and installation techniques. For these reasons we recommend an evaluation of these systems by a licensed electrician.

LIGHTS/OUTLETS

A RANDOM SAMPLE OF ELECTRICAL OUTLETS AND SWITCHES ARE INSPECTED THROUGHOUT THE STRUCTURE. NOT ALL OUTLETS AND SWITCHES ARE NECESSARILY ACCESSABLE TO THE INSPECTOR. ANY APPARENT DEFICIENCIES DISCOVERED ARE NOTED ON THE INSPECTION FORM FOR THE ROOM WHERE THE SWITCH OR OUTLET IS LOCATED

SMOKE DETECTORS

Smoke detectors should be checked periodically to insure they are functioning properly

PLUMBING

COMMENTS

THE WATER MAIN LEAKS ABOVE THE GATE VALVE

Water Pipes						X
Drain Pipes	X					
Vent Pipes	X					
Laundry Tub		X				
Tub Pump		X				
Pressure	X					
Water Heater	X					
Exhaust		X				
Relief Valve	X					

A	N	N	M	D
C	P	I	A	E
C	R	N	R	F

WATER SOURCE: PUBLIC PRIVATE
 SEWAGE SERVICE: PUBLIC PRIVATE
 WATER SERVICE ON: YES NO

WATER MAIN/PIPES MAIN: Galvanized Copper PVC; Other: _____
 PIPES: Galvanized Copper PVC; Other: _____

- Some/most plumbing concealed
- Apparent leaks noted
- Valve corroded/inoperative
- Water hammer noted
- Strapping recommended
- Copper/galvanized contact noted
- Hose faucet damaged/inoperative/leaking
- Hose faucet not self draining

DRAIN/VENT PIPES Cast iron Galvanized Lead Plastic Undetermined

- Some/most plumbing concealed
- Moderate/heavy corrosion noted
- No apparent/covered floor drain
- Cracked pipe
- No/negative fall
- Apparent leaks
- No accessible cleanouts

LAUNDRY FACILITIES Location: KITCHEN

Energy sources provided: Gas 120 volt electric 220 volt electric
 Features present: Sink Drain (floor) Drain (grey box) Vent Water faucets with shutoff valves

WATER HEATER

Heater	LOCATION	SIZE	FUEL	AGE
#1	<u>INTERIOR CLOSET</u>	<u>50 GAL</u>	<u>ELECTRIC</u>	<u>5 YRS</u>

Pilot/electric off. Heater inaccessible
 The inspector does not restore utilities or light pilots. Inspections with utilities or pilots off are very limited. TPR valves and drains are not operated as they are prone to leak following testing. The remaining useful life of a water heater cannot be predicted.

- Apparent leak noted
- Gas valve missing/inaccessible
- Damaged/corroded case.
- Rust flakes on/around burner
- No TPR valve installed
- Apparent improper installation
- TPR valve extension missing
- Apparent insufficient ventilation
- Access cover missing
- Corrosion on connectors
- Copper/flexible gas supply line

HEATING

COMMENTS

Operation	<input checked="" type="checkbox"/>				
Draft Control	<input checked="" type="checkbox"/>				
Exhaust System	<input checked="" type="checkbox"/>				
Distribution	<input checked="" type="checkbox"/>				
Fuel tank/lines	<input checked="" type="checkbox"/>				
Thermostat	<input checked="" type="checkbox"/>				
Blower	<input checked="" type="checkbox"/>				
Humidifier		<input checked="" type="checkbox"/>			
Heat exchanger	<input checked="" type="checkbox"/>				
Relief Valve		<input checked="" type="checkbox"/>			
Circulator pump		<input checked="" type="checkbox"/>			
Air Conditioning	<input checked="" type="checkbox"/>				

____ UTILITIES/PILOTS OFF AT TIME OF INSPECTION

Inspector does not restore utility service and does not light pilots. Inspections with utilities or pilots off are very limited. The inspector cannot definitively detect heat exchanger cracks and holes. This can only be accomplished by dismantling the system.

HEATING

	LOCATION	TYPE	FUEL	APPROX BTUs	APPROX AGE	DESIGN LIFE
SYSTEM # 1	EAST EXTERIOR	FORCED AIR	GAS	90,000	8 YRS	20 YRS
SYSTEM # 2						
SYSTEM # 3						

- | | | |
|-----------------------------------------------------------------------|---------------------------------------|-------------------------------------------|
| <input checked="" type="checkbox"/> Unit fully/partially inaccessible | ____ Electronic ignition malfunctions | ____ Closed unit/unable to inspect burner |
| ____ Pilot not is/NOT tested | ____ Apparent improper installation | ____ Unusual flame pattern observed |
| ____ Does not respond to controls | ____ Makes excessive/unusual noise | ____ Flame fluctuates when fan comes on |
| ____ Damaged/inoperative controls | ____ Recommend clean and check | ____ Rust flakes in combustion chamber |

VENTING/COMBUSTION AIR

- | | | |
|----------------------------------------------------------------------------|-----------------------------------------------|----------------------------------------------------------|
| <input checked="" type="checkbox"/> Flue vent fully/partially inaccessible | ____ Apparent backventing noted | ____ Moderate/excessive corrosion on vent/draft diverter |
| ____ Inadequate vent clearance/height | ____ Apparent improper flue vent installation | ____ Apparent insufficient combustion air available |

DISTRIBUTION SYSTEM/FILTERS

- | | | |
|---------------------------------|----------------------------------------|-------------------------------------------|
| ____ Ducts largely concealed | ____ Moderate/excessive duct corrosion | ____ Missing/damaged register grill |
| ____ Damaged/disconnected ducts | ____ Additional strapping recommended | ____ Missing/damaged/improper size filter |
| ____ Apparent low air volume | ____ Air leaks at joints | ____ Missing/damaged filter clip |

AIR CONDITIONING

____ COULD NOT BE OPERATED, OUTSIDE TEMPERATURE WAS TOO LOW

	LOCATION	TYPE	FUEL	APPROX BTUs	APPROX AGE	DESIGN LIFE
SYSTEM # 1	EAST EXTERIOR	CENTRAL AIR	ELECT	4 TON	8 YRS	20 YRS
SYSTEM # 2						

- | | | |
|---------------------------------|--------------------------------------|-------------------------------------------|
| ____ Unit makes excessive noise | ____ Condenser airflow obstructed | ____ Apparent freon/condensate line leaks |
| ____ Visible damage to unit | ____ Unsatisfactory temperature drop | ____ Outside unit not level |

FOUNDATION/STRUCTURE

COMMENTS

Foundation	X				
Beams	X				
Bearing Walls	X				
Joists/Trusses	X				
Piers/Posts	X				
Floor/Slab	X				
Sump/Sump Pump	X	X			
Heat	X				

A	N	N	M	D
C	P	I	A	E
C	R	N	R	F

FOUNDATION

BASEMENT

- None/partial
- Brick Poured concrete Brick Stone
- Common/large cracks
- Moderate/excessive deterioration
- Minor/major efflorescence
- Areas inaccessible/concealed/uninspected

CRAWL SPACE

- None/partial
- No/blocked access
- No vents
- Vents blocked
- Apparent moisture/no vapor barrier
- Areas inaccessible/concealed/uninspected

SLAB

- None/partial/garage only
- Common cracks
- Large cracks
- Uneven/sloped floors
- Small/large areas covered

STRUCTURE

Wood frame Steel frame Brick Stone Other _____

- Cracked/broken/sagging structural members
- Excessive floor sloping
- Leaking/unsecured/missing posts/piers
- Evidence of shrinking/repair

MOISTURE EVIDENCE/CONTROL

- Evidence of ongoing water penetration
- Efflorescence
- Sump pump installed
- Location: _____
- Sump pump appears inoperative

Evidence of ongoing foundation water penetration can easily be concealed, either intentionally or unintentionally by a home occupant. Further, if there has been a dry period prior to the inspection, evidence of past water penetration may not be visible or detectable.

DOORS, STAIRS, HALLWAYS

COMMENTS

THE BASE OF THE WATER HEATER CLOSET DOOR DRAGS ON THE FLOOR

Exterior Doors					X
Interior Doors					X
Entryway	X				
Stairs	X				
Hallways	X				

A	N	N	M	D
C	P	I	A	E
C	R	N	R	F

DOORS

ENTRYWAY, STAIRS, HALLWAYS

ATTIC

A	N	N	M	D
C	P	I	A	E
C	R	N	R	F

COMMENTS

Framing	<input checked="" type="checkbox"/>				
Sheathing	<input checked="" type="checkbox"/>				
Ventilation	<input checked="" type="checkbox"/>				
Attic fan	<input checked="" type="checkbox"/>				
Whole house fan	<input checked="" type="checkbox"/>				
Insulation	<input checked="" type="checkbox"/>				

METHOD OF INSPECTION: None/no access Complete access Limited access (low clearance, obstructions) From access only

EVIDENCE OF ONGOING WATER PENETRATION? yes no, Location: _____
 Water penetration can be conclusively determined only if it is raining at the time of inspection. Dry at time of inspection? yes no

FRAMING/ SHEATHING

Cracked/broken/sagging structural member Evidence of moisture damage/dry rot/other damage
 Cracked/damaged/missing access panel

VENTILATION/ ATTIC FAN/ WHOLE HOUSE FAN

No/minimal ventilation Torn/missing vent screens Fan inoperative
 Vents blocked Dryer/ exhaust fans vented into attic Fan is slow/noisy

INSULATION Batt/roll Loose fill Rigid board, other: _____
 Uneven distribution/partially missing No moisture barrier apparent

GARAGE

A	N	N	M	D
C	P	I	A	E
C	R	N	R	F

COMMENTS

AN APPROX 15" X 30" OPENING NOTED IN THE SOUTH WALL EXPOSING THE WALL CAVITY

Door	<input checked="" type="checkbox"/>				
Door opener	<input checked="" type="checkbox"/>				
Ceiling/walls					<input checked="" type="checkbox"/>
Floor	<input checked="" type="checkbox"/>				
WINDOW	<input checked="" type="checkbox"/>				

DOOR/DOOR OPENER Metal Wood/composite Other _____
 Automatic opener yes no; Operates properly (including automatic reverse) yes no;
 Weather seal damaged/missing Apparent damage/moisture damage Window cracked/damaged/missing
 Door appears out of adjustment/alignment

CEILING/WALLS Ceiling - Drywall Plaster Acoustic spray Other SHEATHING
 Walls - Drywall Plaster Paneling; Other: _____
 Common cracks Apparent moisture stains Apparent damage Full inspection obstructed
 Large/unusual cracks Damaged/loose trim Apparent patching Outlet damaged/defective
 Outlets not GFI protected

PEDESTRIAN DOOR/WINDOWS
 Windows: Double hung Casement Sliding Fixed Other _____
 Damaged/broken/inoperative window Damaged/inoperative door

FLOOR Common cracks Large/unusual cracks Heaving/settling