DocuSign Envelope ID: 78E4E73E-CED6-4F61-BB2E-F02C48B4AAED STANDARD NOTICE OF WORK COMPLETED AND NOT COMPLETED

NOTICE - All recommendations may not have been completed - See Below - Recommendations not completed. This form is prescribed by the Structural Pest Contol Board

Building No. 1222	Street Swan Lake Drive	City Fairfield	Zip 94533	Date of Completion 01/10/2024
F	Twin Termite and P 3720 Madison Aver North Highlands, C Phone: (707) 455-89 www.twintermite.co Registration # PR53	nue #100 A 95660 946 Fax: (916) 344-8942 om	Julie	gned by: A. Browssard Report # 89001 PS3B9ED43E 24 10:41 PM PST
Ordered by: Windy Rodriguez		Property Owner and/or Party of Interest:		Report Sent to:

The following recommendation on the above designated property, as outlined in Wood Destroying Pests and Organisims Inspection Report Dated <u>12/20/2023</u> have been and/or have been not completed.

Recommendations completed by this firm are in accordance with the Structural Pests Control Board Rules and Regulations: ITEM(S) 3A, 3B, 3C						
Recommendations completed by this firm that are considered secondary and substar Regulations including person requesting secondary measure:	idard measures under Section 1993 of the Struction	ural Pests Control Board Rules and				
Cost of Work Completed:						
	Cost:	\$1,720.98				
	Inspection Fee:	\$0.00				
	Other:	\$0.00				
	Total:	\$1,720.98				
Recommendations not completed by this firm: 4A, 4B, 4C, 4D, 5A						
Estimated Cost:						
Remarks: THIS IS TO CERTIFY THAT THE PROPERTY DESCRIBED HERE INFECTION IN THE VISIBLE AND ACCESSIBLE AREAS EXCEPT SECTION 1 CLEARANCE.						

Dada

Signature

You are entitled to obtain copies of all reports and completion notices on this properly reported to the board during the proceeding two years upon payment of service fee to: Structural Pest Control Board 2005 Evergreen Street, Suite 1500, Sacremento, CA 95815.

NOTE: questions or problems concering the above report should be directed to the manager of this company. Unsolved questions or problems with services performed may be directed to the Structural Pest Control Board at (916) 561-8708 - (800) 737-8188 or www.pestboard.ca.gov 43M-44 (Rev. 10/01)