

**GOVEA ROOFING CO.
ROOF CERTIFICATION/ROOF CLEARANCE**

Work Ordered BY: WENDY RODRIGUEZ	Agent:	Agent:
Title Company:	Escrow Officer:	Escrow #
Completion notices for: 107 GLACIER CIRCLE VACAVILLE CA 95687	Number of Repairs. \$ 0	
		Date: 05/ 10/2023

This is to state that the work recommended per roof inspection report for the above address is complete.

In my opinion with proper maintenance on the roof. This roof has a useful life of 22 yrs. Roof cert/clearance duration 2 years.



Jose Govea, GOVEA ROOFING COMPANY, this roof inspection is not deemed in any way to be a representation, guarantee or certification by GOVEA ROOFING as to the water tightness of the existing roof system, but rather a statement of the opinion of GOVEA ROOFING of the current condition of the roof on the date of the inspection. For such representation, guarantee or certification, the buyer should rely solely on the statement of the sellers.

GOVEA ROOFING, by making this clearance, is not acting as agent for the buyers or sellers in the purchase or sale of the inspected property.

x 